

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-18"	0-32"	0-34"	0-30"	0-14"									
Texture Group	.1941(A)(1)	C	C/L	C	C	SCL									
Consistence	.1941	FR		FR	FR	VFR									
Structure	.1941(A)(2)	SBK		SBK	SBK	SBK									
Mineralogy	.1941(A)(3)	S/S		SS/SP	SS/SP	SS/SP									
HORIZON 2 DEPTH		18"	32"	34"	30"	14-20"									
Texture Group	.1941(A)(1)	<del>SAP</del>	SAP	SAP	SAP	C									
Consistence	.1941	SAP				FR									
Structure	.1941(A)(2)					SBK									
Mineralogy	.1941(A)(3)					S/S									
HORIZON 3 DEPTH						40"									
Texture Group	.1941(A)(1)					SAP									
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948			P3	P3	P3									
LONG TERM ACCEPTANCE RATE	.1955			3	3	3									

3/14/03

- NEED HOUSE CORNERS MARKED
- NEED PITS TO VERIFY SOIL DEPTH