

HTE 03-5-6556

16176

# OPERATIONS PERMIT

Name: (owner) Johnnie Canady  New Installation  Septic Tank  
 Property Location: SR# 1115  Repairs  Nitrification Line  
 Subdivision Lake Crestview Lot # 9  
 Tax ID # \_\_\_\_\_ Quadrant # \_\_\_\_\_  
 Contractor: Datten Backhoe Registration # \_\_\_\_\_

Basement with Plumbing:  Garage:   
 Water Supply:  Well  Public  Community  
 Distance From Well: 50 ft.

**Following are the specifications for the sewage disposal system on above captioned property.**

Type of system:  Conventional  Other \_\_\_\_\_  
 Size of tank: Septic Tank: 600 gallons Pump Tank: \_\_\_\_\_ gallons  
 Subsurface Drainage Field No. of ditches 4 exact length of each ditch 70 ft. width of ditches 3 ft. depth of ditches 18-24 in.  
 French Drain Required: \_\_\_\_\_ Linear feet

Date: 7-17-03  
 Inspected by: J. L. ARS  
 Environmental Health Specialist

PERMIT NO. 20040

