

OPERATIONS PERMIT 03-56571

Name: (owner) Danny Neece

New Installation Septic Tank
 Repairs Nitrification Line

Property Location: SR# 1115
Subdivision Peperlan

Lot # 149
Quadrant # _____

TAX ID# _____
Contractor: Ted Brown

Registration # _____

Basement with Plumbing:

Garage:

*Lines OK Tanks OK
Needs Alarm / Alarm Box
And Pump check*

Water Supply: Well Public Community

Distance From Well: _____ ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other Pump to Conv.

Size of tank: Septic Tank: 1000 gallons Pump Tank: 1000 gallons

Subsurface Drainage Field: No. of ditches 1 exact length of each ditch 300 ft. width of ditches 3 ft. depth of ditches 18-24 in.

French Drain: _____ Linear feet

PERMIT NO. 19261

Date: 6-17-03

Inspected by: J. Waters
Environmental Health Specialist

Vally View Rd To 52115

