

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

D

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-48"	0-40"											
Texture Group	.1941(A)(1)	LS	LS											
Consistence	.1941	VFR	VFR											
Structure	.1941(A)(2)	G	C											
Mineralogy	.1941(A)(3)	MS/MP	MS/MP											
HORIZON 2 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 3 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 4 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/.1956													
CLASSIFICATION	.1948	P3	B											
LONG TERM ACCEPTANCE RATE	.1955	.8	2											

1x

4

N 85°00'00"E 196.27'

N 05°07'50"W 100.00'


3

0.45 AC.

PROPOSED
* SEPTIC TANK
LOCATION

PROPOSED
HOUSE
LOCATION

PROPOSED DRIVE



S 05°00'00"E 100.00'

CON.
REPAIR

SITE PLAN APPROVAL

DISTRICT RR03 USE SFD

#BEDROOMS 4

Date 4/2/03
Zoning Administrator [Signature]

S 85°00'00"W 196.04'

C