

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

D

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-40"	0"	0-16"							
Texture Group	.1941(A)(1)	sh		SL							
Consistence	.1941	VFR		VFR							
Structure	.1941(A)(2)	G/CR		S							
Mineralogy	.1941(A)(3)	NS/NP		NS/NP							
HORIZON 2 DEPTH				16-36"							
Texture Group	.1941(A)(1)			SC							
Consistence	.1941			F							
Structure	.1941(A)(2)			SBR							
Mineralogy	.1941(A)(3)			S/P							
HORIZON 3 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942	24"		30"							
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948	P5		P5							
LONG TERM ACCEPTANCE RATE	.1955	.8		.3							

• #2 - SATURATED SOIL
AUGER PUSHED DOWN

• SITE NOT CLEARED PAST HOUSE

