

COMMENTS:

BM 2/21/2011 Made a site visit and observed that a fence post had been put on top of the supply line connecting the septic tank to the drain line.

BM 2/22/2011 Called & left message w/ Mr. Maples (Maples Septic) about no permit needed, but to call if he wanted me to check his work.

3/2/2011 Met Mr. Maples on the property the first 10 or 12 ft. of chamber had been crushed. Will call when ready for inspection.

3/3/2011 The first 20 ft. of the chamber system was ~~etc~~ crushed. Met with Mr. Maples & he replaced the chamber.