PREPARED 3/24/09, 13:59:38 INSPECTION TICKET PAGE Harnett County INSPECTOR: IVR DATE 3/25/09 ADDRESS . : 5920 US 401 N SUBDIV: CONTRACTOR : PHONE : OWNER . . : MCDOUGALD JESSIE H & JOELINA G PHONE : PARCEL . : 08-0655- - -0136- - -APPL NUMBER: 08-50020908 CP DAYCARE DIRECTIONS: US 401N. NEAR 5920 US 401. 401N TOWARS FUQUAY 4 MI ON RIGHT. T/S: 09/12/2008 01:47 PM VBROWN ----STRUCTURE: 000 000 DAYCARE 90PRESCHOOLERS, 35AFT 15EMP FLOOD ZONE . . . : FLOOD ZONE X PROPOSED USE . . . . . . : DAYCARE SEPTIC - EXISTING? . . . : NEW TANK WATER SUPPLY . . . . . . : COUNTY

PERMIT: CBCO 00 CP BUILDING COMMERCIAL

REQUESTED INSP DESCRIPTION

TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

C151 01 3/25/09 TI\_ C\*BLDG FOOTING VRU #: 001747245

3.25-09 **APRS** 

COMMENTS AND NOTES -----

Joe E. Godwin Sr., P.E., P.L.S.

Kovin R. Allen, P.E.

Consulting Engineers & Surveyors

1403 NC IIwy 50 South Benson, NC 27504

Phone: (919) 894-5731 (919) 894-7765

Fax: (919) 894-8190

Email: juest@enochengineers.com

March 24, 2009

Naylor Construction, Inc. 289 Shaw Pond Road Newton Grove, NC 28366 Attn: Robert Naylor

RE: Compaction Test Results

Subject: Lilly Pad Daycare,

Highway 401 Lillington, NC

Dear Mr. Naylor:

Please find the enclosed compaction test results on the above referenced project for your review and use. Should you have any further questions please feel free to contact us at the above listed number.

Josh for

F. Godwin, St., P.E. ch Engineers, P.A.

## Enoch Engineers 1403 NC 50 S Benson, NC 27504

Compaction Test Results
ASTM D 2167

Naylor Construction, Inc.
Lilly Pad Day Care

Lillington, NC

	Volume of Hole (ft <sup>-1</sup> )	Comp. Volume of Soll (nº 3) Depth (in)	Depth (in)	Location	Moisture Content (%)	Compaction %
	0.03225	0.03125	8.0	Building Pad, Center	NT	96.9
22						
w		:				
4						
5						
O						
7						
8						
9						
6						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
) N						

Notes: "a, b, c" indicates retest of failing location.

NT = not tested for.

08500

#### **DETTER & ASSOCIATES**

Consulting Engineer

Post Office Box 53827
Fayetteville, N C 28305
910/485-7778:voice
910/485-5883:fax

e-mail: jamesdetter@embarqmail.com

#### FACSIMILE (total of 2 pages including this cover page)

November 5, 2008

To: Lynwood McDonald, Building Codes Administrator Inspections Department Harnett County P. O. Box 65
Lillington N C 27546
Fax: 910.814.6459

FROM: James D. Detter, P. E


RE: Lillypads Child Development Center. U. S. Hwy 401 Lillington, N C

Attached is a drawing of a portion of drawing P-200. An interior hose bibb (P-10 in the fixture schedule) is being added to the Kitchen 113 and Laundry/Stor. 112 in lieu of a trap primer as a means of providing a water seal in the trap of the floor drain that is in each of these two rooms.

Attachment as

Cc: Robert Naylor, Owner

SEAN ACINES DE L'ALIMANTE DE L



Detter & Associates

PREPARED 4/02/09, 13:59:24 INSPECTION TICKET PAGE INSPECTOR: IVR Harnett County DATE 4/03/09 ADDRESS . : 5920 US 401 N SUBDIV: CONTRACTOR : PHONE : OWNER . . : MCDOUGALD JESSIE H & JOELINA G PHONE : PARCEL . . : 08-0655- - -0136- - -APPL NUMBER: 08-50020908 CP DAYCARE DIRECTIONS : US 401N. NEAR 5920 US 401. 401N TOWARS FUQUAY 4 MI ON RIGHT. T/S: 09/12/2008 01:47 PM VBROWN ----STRUCTURE: 000 000 DAYCARE 90PRESCHOOLERS, 35AFT 15EMP FLOOD ZONE . . . : FLOOD ZONE X PROPOSED USE . . . . . : DAYCARE SEPTIC - EXISTING? . . . . : NEW TANK WATER SUPPLY . . . . . : COUNTY \_\_\_\_\_\_ PERMIT: CPEC 00 CP ELECTRICAL COMMERCIAL

REQUESTED INSP DESCRIPTION

TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

E267 01 4/03/09 TI C\*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 001750801

PREPARED 4/14/09, 13:59:10 INSPECTION TICKET PAGE Harnett County INSPECTOR: IVR DATE 4/15/09 \_\_\_\_\_\_ ADDRESS . : 5920 US 401 N SUBDIV: CONTRACTOR : PHONE : OWNER . . : MCDOUGALD JESSIE H & JOELINA G PHONE : PARCEL . . : 08-0655- - -0136- - -APPL NUMBER: 08-50020908 CP DAYCARE DIRECTIONS : US 401N. NEAR 5920 US 401. 401N TOWARS FUQUAY 4 MI ON RIGHT. T/S: 09/12/2008 01:47 PM VBROWN ----STRUCTURE: 000 000 DAYCARE 90PRESCHOOLERS, 35AFT 15EMP FLOOD ZONE . . . : FLOOD ZONE X PROPOSED USE . . . . . . : DAYCARE SEPTIC - EXISTING? . . . : NEW TANK WATER SUPPLY . . . . . : COUNTY PERMIT: CPPC 00 CP PLUMBING COMMERCIAL REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

P357 01 4/15/09 TI C\*PLUMB UNDER SLAB VRU #: 001755318
4:15-09 DPB

PREPARED 4/15/09, 14:00:57 INSPECTION TICKET PAGE Harnett County INSPECTOR: IVR DATE

ADDRESS . : 5920 US 401 N CONTRACTOR :

PHONE : OWNER . . : MCDOUGALD JESSIE H & JOELINA G PHONE :

PARCEL . . : 08-0655- - -0136- - -APPL NUMBER: 08-50020908 CP DAYCARE

DIRECTIONS : US 401N. NEAR 5920 US 401. 401N

TOWARS FUQUAY 4 MI ON RIGHT.

T/S: 09/12/2008 01:47 PM VBROWN ----PLEASE CALL CAMERON ADCOCK AFTER YOU DO THE INSPECTION SO THEY CAN CALL THE EL ECTRICAL CONTRACTOR TO COME. 814-7195.

SUBDIV:

STRUCTURE: 000 000 DAYCARE 90PRESCHOOLERS, 35AFT 15EMP

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE . . . . . : DAYCARE SEPTIC - EXISTING? . . . : NEW TANK

WATER SUPPLY . . . . . . : COUNTY

PERMIT: CPPC 00 CP PLUMBING COMMERCIAL

REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

C\*PLUMB UNDER SLAB VRU #: 001755318

no plans at jobsite. \$50 reinspection fee 4/15/09

P357 02 4/16/09 C\*PLUMB UNDER SLAB VRU #: 001756162

----- COMMENTS AND NOTES -C

Adoock after inspecting so they can get the electrician out. 814-7195

4/16/09

PREPARED 4/16/09, 13:58:56 INSPECTION TICKET PAGE Harnett County INSPECTOR: IVR DATE

ADDRESS . : 5920 US 401 N

SUBDIV:

4/17/09

21

PHONE :

CONTRACTOR :

OWNER . . : MCDOUGALD JESSIE H & JOELINA G

PHONE :

APPL NUMBER: 08-50020908 CP DAYCARE

PARCEL . . : 08-0655- - -0136- - -

DIRECTIONS: US 401N. NEAR 5920 US 401. 401N

TOWARS FUQUAY 4 MI ON RIGHT.

T/S: 09/12/2008 01:47 PM VBROWN ----PLEASE CALL CAMERON ADCOCK AFTER YOU DO THE INSPECTION SO THEY CAN CALL THE EL

ECTRICAL CONTRACTOR TO COME. 814-7195.

150026#28706

STRUCTURE: 000 000 DAYCARE 90PRESCHOOLERS, 35AFT 15EMP

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE . . . . . . : DAYCARE

SEPTIC - EXISTING? . . . : NEW TANK

WATER SUPPLY . . . . . . : COUNTY

PERMIT: CPEC 00 CP ELECTRICAL COMMERCIAL

REQUESTED INSP DESCRIPTION

COMPLETED RESULT RESULTS/COMMENTS TYP/SQ 

4/03/09 BS

E267 01

C\*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 001750801

4/03/09 AP E259 01 4/17/09 ŢĮ\_

C\*ELEC UNDER SLAB VRU #: 001756717

MR. TOMMY WOULD LIKE YOU TO GO AS LATE AFTER LUNCH AS

POSSIBLE. \*\*\*\*\*\*\*\*\*

\*\*\*\*\*\*\*\*\*

INSPECTION TICKET PREPARED 4/21/09, 13:58:53 INSPECTOR: IVR Harnett County

SUBDIV:

PAGE DATE 4/22/09

ADDRESS : : 5920 US 401 N CONTRACTOR :

PHONE : PHONE :

OWNER . . : MCDOUGALD JESSIE H & JOELINA G

PARCEL . .: 08-0655- - -0136- - -

APPL NUMBER: 08-50020908 CP DAYCARE

DIRECTIONS: US 401N. NEAR 5920 US 401. 401N

TOWARS FUQUAY 4 MI ON RIGHT.

T/S: 09/12/2008 01:47 PM VBROWN ----PLEASE CALL CAMERON ADCOCK AFTER YOU DO THE INSPECTION SO THEY CAN CALL THE EL ECTRICAL CONTRACTOR TO COME. 814-7195.

\_\_\_\_\_\_

STRUCTURE: 000 000 DAYCARE 90PRESCHOOLERS, 35AFT 15EMP

FLOOD ZONE . . . : FLOOD ZONE X

SEPTIC - EXISTING? . . . . : NEW TANK PROPOSED USE . . . . . : DAYCARE

WATER SUPPLY . . . . . . : COUNTY

PERMIT: CBCO 00 CP BUILDING COMMERCIAL

REQUESTED INSP DESCRIPTION COMPLETED RESULT RESULTS/COMMENTS TYP/SQ \_\_\_\_\_\_

C\*BLDG FOOTING VRU #: 001747245 3/25/09 BS C151 01

3/25/09 AP compaction test attached 4/16/09 TI ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001756360 A814 01

C\*BLDG SLAB INSP VRU #: 001758495 4/22/09 TI C159 01 4.22-09

----- COMMENTS AND NOTES ---------

PREPARED 6/09:09, 13:59:36 INSPECTION TICKET PAGE 13 Harnett County i INSPECTOR: IVR DATE 6/10/09 ADDRESS . : 592 US 401 N SUBDIV: CONTRACTOR : PHONE : OWNER . . : MCDOUGALD JESSIE H & JOELINA G PHONE : PARCEL . . : 08-0655- - -0136- - -APPL NUMBER: 08-50020908 CP DAYCARE DIRECTIONS: US 401N. NEAR 5920 US 401. 401N TOWARS FUQUAY 4 MI ON RIGHT. T/S: 09/12/2008 01:47 PM VBROWN ----PLEASE CALL CAMERON ADCOCK AFTER YOU DO THE INSPECTION SO THEY CAN CALL THE EL ECTRICAL CONTRACTOR TO COME. 814-7195. STRUCTURE: 000 000 DAYCARE 90PRESCHOOLERS, 35AFT 15EMP FLOOD ZONE . . . : FLOOD ZONE X PROPOSED USE . . . . . : DAYCARE SEPTIC - EXISTING? . . . : NEW TANK WATER SUPPLY . . . . . : COUNTY PERMIT: CBCO 00 CP BUILDING COMMERCIAL REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS C151 01 3/25/09 BS C\*BLDG FOOTING VRU #: 001747245 3/25/09 AP compaction test attached 4/16/09 TI A814 01 ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001756360 4/24/09 AP 5976 US 401 N C159 01 4/22/09 BS 4/22/09 AP C153 01 TI 6/10/09 C\*BLDG ROUGH IN TIME: 17:00 VRU #: 001779321 PERMIT: CPEC 00 CP ELECTRICAL COMMERCIAL REQUESTED INSP DESCRIPTION TYP/SO COMPLETED RESULT RESULTS/COMMENTS ------E267 01 4/03/09 BS C\*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 001750801 4/03/09 AΡ E259 01 4/17/09 BS C\*ELEC UNDER SLAB VRU #: 001756717 4/17/09 AΡ MR. TOMMY WOULD LIKE YOU TO GO AS LATE AFTER LUNCH AS POSSIBLE. \*\*\*\*\*\*\*\*\* \*\*\*\*\*\*\*\*\* E251 01 6/10/09 TI C\*ELEC ROUGH IN TIME: 17:00 VRU #: 001779339 PERMIT: CPMC 00 CP MBCHANICAL COMMERCIAL REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS -----BS M459 01 6/09/09 C\*MECH ROUGH IN VRU #: 001779008 6/08/09 CA M459 02 6/10/09 TI C\*MECH ROUGH IN TIME: 17:00 VRU #: 001779347 PERMIT: CPPC 00 CP PLUMBING COMMERCIAL

INSP DESCRIPTION

RESULTS/COMMENTS

RESULT

REQUESTED

COMPLETED

TYP/SQ

PREPARED 6/09/09, 13:59:36
Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 6/10/09

ADDRESS . : 592) US 401 N SUBDIV:

PHONE :

CONTRACTOR :: Q. OWNER . . : MCDOUGALD JESSIE H & JOELINA G

PARCEL . . : 08-0655- - -0136- - - APPL NUMBER: 08-50020908 CP DAYCARE

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P357 01	4/15/09 4/15/09	BS DP	C*PLUMB UNDER SLAB VRU #: 001755318 no plans at jobsite. \$50 reinspection fee
P357 02	4/16/09 4/16/09	BS AP	C*PLUMB UNDER SLAB VRU #: 001756162
P351 01	6/10/09	DABS	C*PLUMB ROUGH IN TIME: 17:00 VRU #: 001779354

PREPARED 6/11/09, 14:06:10 INSPECTION TICKET PAGE INSPECTOR: IVR Harnett County DATE 6/12/09

PHONE :

ADDRESS . : 5920 US 401 N SUBDIV: CONTRACTOR : 🔭 PHONE :

PARCEL . . : 08-0655- - -0136- - -APPL NUMBER: 08-50020908 CP DAYCARE

DIRECTIONS : US 401N. NEAR 5920 US 401. 401N

OWNER . . : MCDOUGALD JESSIE H & JOELINA G

TOWARS FUQUAY 4 MI ON RIGHT.

T/S: 09/12/2008 01:47 PM VBROWN ----PLEASE CALL CAMERON ADCOCK AFTER YOU DO THE INSPECTION SO THEY CAN CALL THE EL ECTRICAL CONTRACTOR TO COME. 814-7195.

STRUCTURE: 000 000 DAYCARE 90PRESCHOOLERS, 35AFT 15EMP

FLOOD ZONE . . . : FLOOD ZONE X

SEPTIC - EXISTING? . . . : NEW TANK PROPOSED USE . . . . . . : DAYCARE

WATER SUPPLY . . . . . : COUNTY

PERMIT: C	BCO 00 CP BI		-
TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
C151 01	•	BS AP	C*BLDG FOOTING VRU #: 001747245
A814 01	4/16/09	TI AP	compaction test attached ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001756360 5976 US 401 N
C159 01	4/22/09	BS	C*BLDG SLAB INSP VRU #: 001758495
C153 01	4/22/09 6/10/09	AP BS	C*BLDG ROUGH IN TIME: 17:00 VRU #: 001779321
C153 02	6/10/09 6/12/09 <b>6-1,3 09</b>	DA) TI APKS	brace trusses per truss documents C*BLDG ROUGH IN TIME: 17:00 VRU #: 001780964
DEDMITE. C		POWDICAL	COMMEDICIAL

PERMIT: C	PEC 00 CP EI REQUESTED COMPLETED	LECTRICAL ( INSP RESULT	COMMERCIAL  DESCRIPTION  RESULTS/COMMENTS
E267 01	4/08/09 4/08/09	BS AP	C*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 001750801
E259 01	4/17/09 4/17/09	BS AP	C*ELEC UNDER SLAB VRU #: 001756717  MR. TOMMY WOULD LIKE YOU TO GO AS LATE AFTER LUNCH AS POSSIBLE. ************************************
E251 01	6/10/09 6/10/09	DA DA	C*ELEC ROUGH IN TIME: 17:00 VRU #: 001779339 need electrical change from 3 phase system to single phase

from engineer to complete electrical inspection. 2. Bond for cold water line must be ahead of shutoff valve E251 02 6/12/09 TIC\*ELEC ROUGH IN TIME: 17:00 VRU #: 001780972

PERMIT:	CPMC	00 CP	MECHANI	CAL	COMMERCIAL	
	REÇ	UESTEI	) INS	₽	DESCRIPTION	
TYP/SQ	COM	PLETEI	) RESU	LT	RESULTS/COMMENTS	
		<b> </b> -			<del></del>	
M459 01	6/	09/09	BS		C*MECH ROUGH IN	VRU #: 001779008
	6/	08/09	CA			
M459 02	6/	10/09	BS		C*MECH ROUGH IN	TIME: 17:00 VRU #: 001779347

INSPECTION TICKET PREPARED 6/11/09, 14:06:10 PAGE 10 Harnett County INSPECTOR: IVR DATE 6/12/09 ADDRESS 4 . : 5920 US 401 N SUBDIV: CONTRACTOR : 7 PHONE : OWNER . . : MCDOUGALD JESSIE H & JOELINA G PHONE : PARCEL . . : 08-0655- - -0136- - -APPL NUMBER: 08-50020908 CP DAYCARE REQUESTED INSP DESCRIPTION
TYP/SQ COMPLETED RESULT RESULTS/COMMENTS need engineers letter on hallway supply duct sourced into 1 6/10/09 boot from 2 different units M459 03 6/12/09 C\*MECH ROUGH IN TIME: 17:00 VRU #: 001780998 6-12-09 PERMIT: CPPC 00 CP PLUMBING COMMERCIAL REQUESTED INSP DESCRIPTION COMPLETED RESULT TYP/SQ RESULTS/COMMENTS -----4/15/09 BS P357 01 C\*PLUMB UNDER SLAB VRU #: 001755318 4/15/09 DP no plans at jobsite. \$50 reinspection fee 4/16/09 BS P357 02 C\*PLUMB UNDER SLAB VRU #: 001756162 4/16/09 AP

allowed for residential aplications

C\*PLUMB ROUGH IN TIME: 17:00 VRU #: 001779354

C\*PLUMB ROUGH IN TIME: 17:00 VRU #: 001780980

Plumbing DWV test must have a 10 foot head. 3 foot is only

P351 01 6/10/09

6/10/09

6.1209 ADBS

P351 02 6/12/09 TI

PREPARED 6/23/09, 13:58:32 INSPECTION TICKET PAGE Harnett County INSPECTOR: IVR DATE 6/24/09 ADDRESS . : 5920 US 401 N SUBDIV: CONTRACTOR : PHONE : OWNER . . : MCDOUGALD JESSIE H & JOELINA G PHONE : PARCEL . . : 08-0655- - -0136- - -APPL NUMBER: 08-50020908 CP DAYCARE DIRECTIONS : US 401N. NEAR 5920 US 401. 401N TOWARS FUQUAY 4 MI ON RIGHT. T/S: 09/12/2008 01:47 PM VBROWN ----PLEASE CALL CAMERON ADCOCK AFTER YOU DO THE INSPECTION SO THEY CAN CALL THE EL ECTRICAL CONTRACTOR TO COME. 814-7195. \_\_\_\_\_\_\_ STRUCTURE: 000 000 DAYCARE 90PRESCHOOLERS, 35AFT 15EMP FLOOD ZONE . . . : FLOOD ZONE X SEPTIC - EXISTING? . . . : NEW TANK PROPOSED USE . . . . . . : DAYCARE WATER SUPPLY . . . . . : COUNTY

PERMIT: CPIC 00 CP INSULATION COMMERCIAL
REQUESTED INSP DESCRIPTION

TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

I185 01 6/24/09 TI C\*INSULATION INSPECTION VRU #: 001785344

PREPARED 7/06/09, 14:03:46 INSPECTION TICKET PAGE Harnett County INSPECTOR: IVR DATE 7/07/09

ADDRESS . : 5920 US 401 N SUBDIV: CONTRACTOR : PHONE : OWNER . . : MCDOUGALD JESSIE H & JOELINA G PHONE :

PARCEL . . : 08-0655- - -0136- - -APPL NUMBER: 08-50020908 CP DAYCARE

DIRECTIONS: US 401N. NEAR 5920 US 401. 401N

TOWARS FUQUAY 4 MI ON RIGHT.

T/S: 09/12/2008 01:47 PM VBROWN ----PLEASE CALL CAMERON ADCOCK AFTER YOU DO THE INSPECTION SO THEY CAN CALL THE EL ECTRICAL CONTRACTOR TO COME. 814-7195.

#### STRUCTURE: 000 000 DAYCARE 90PRESCHOOLERS, 35AFT 15EMP

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE . . . . . . : DAYCARE SEPTIC - EXISTING? . . . : NEW TANK

WATER SUPPLY . . . . . : COUNTY

PERMIT: CPPC 00 CP PLUMBING COMMERC	CIAL
-------------------------------------	------

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P357 01	4/15/09 4/15/09	BS DP	C*PLUMB UNDER SLAB VRU #: 001755318  no plans at jobsite. \$50 reinspection fee
P357 02	4/16/09 4/16/09	BS AP	C*PLUMB UNDER SLAB VRU #: 001756162
P351 01	6/10/09 6/10/09	BS DA	C*PLUMB ROUGH IN TIME: 17:00 VRU #: 001779354 Plumbing DWV test must have a 10 foot head. 3 foot is only allowed for residential aplications
P351 02	6/12/09 6/12/09	BS AP	C*PLUMB ROUGH IN TIME: 17:00 VRU #: 001780980
P357 03	7/07/09 <b>7-7-09</b>	APKS_	C*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001790807 T/S: 07/06/2009 01:15 PM JBROCK

PREPARED 7/08/09, 14:03:32 INSPECTION TICKET PAGE 5
Harnett County INSPECTOR: IVR DATE 7/09/09

TABLETOR: 1VR DATE 1/05/0

PHONE :

ADDRESS . : 5976 US 401 N SUBDIV: CONTRACTOR : PHONE :

PARCEL . . : 08-0655- - -0136- -02-APPL NUMBER: 08-50020908 CP DAYCARE

DIRECTIONS: US 401N. NEAR 5920 US 401. 401N

BS

OWNER . . : MCDOUGALD JESSIE H & JOELINA G

TOWARS FUQUAY 4 MI ON RIGHT.

T/S: 09/12/2008 01:47 PM VBROWN ---PLEASE CALL CAMERON ADCOCK AFTER YOU DO
THE INSPECTION SO THEY CAN CALL THE EL
ECTRICAL CONTRACTOR TO COME. 814-7195.

\_\_\_\_\_\_

STRUCTURE: 000 000 DAYCARE 90PRESCHOOLERS, 35AFT 15EMP

FLOOD ZONE . . . : FLOOD ZONE X
PROPOSED USE . . . . . . . : DAYCARE

PROPOSED USE . . . . . : DAYCARE SEPTIC - EXISTING? . . . . : NEW TANK

WATER SUPPLY . . . . . . . COUNTY

4/16/09

P357 02

PERMIT: CPPC 00 CP PLUMBING COMMERCIAL

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P357 01	4/15/09 4/15/09	BS DP	C*PLUMB UNDER SLAB VRU #: 001755318 no plans at jobsite. \$50 reinspection fee

C\*PLUMB UNDER SLAB VRU #: 001756162

4/16/09 AP
P351 01 6/10/09 BS C\*PLUMB ROUGH IN TIME: 17:00 VRU #: 001779354
6/10/09 DA Plumbing DWV test must have a 10 foot head. 3 foot is only

allowed for residential aplications

P351 02 6/12/09 BS C\*PLUMB ROUGH IN TIME: 17:00 VRU #: 001780980

For the addition of the kitchen grese trap drains------P355 01 7/09/09 TI C\*PLUMB SEWER CONNECTION TIME: 17:00 VRU #: 001791953

PREPARED 8/04/09, 14:22:02 INSPECTION TICKET PAGE 10 Harnett County INSPECTOR: IVR DATE 8/05/09

ADDRESS . : 5976 US 401 N SUBDIV: CONTRACTOR : PHONE : OWNER . . : MCDOUGALD JESSIE H & JOELINA G PHONE :

PARCEL . . : 08-0655- - -0136- -02-APPL NUMBER: 08-50020908 CP DAYCARE

DIRECTIONS: US 401N. NEAR 5920 US 401. 401N

TOWARS FUQUAY 4 MI ON RIGHT.

T/S: 09/12/2008 01:47 PM VBROWN ---PLEASE CALL CAMERON ADCOCK AFTER YOU DO
THE INSPECTION SO THEY CAN CALL THE EL
ECTRICAL CONTRACTOR TO COME. 814-7195.

\_\_\_\_\_\_\_

STRUCTURE: 000 000 DAYCARE 90PRESCHOOLERS, 35AFT 15EMP

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE . . . . : DAYCARE SEPTIC - EXISTING? . . . . : NEW TANK

WATER SUPPLY . . . . . : COUNTY

PERMIT: CPPC 00 CP PLUMBING COMMERCIAL REQUESTED INSP DESCRIP

	REQUESTED	INSP	DESCRIPTION
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS
P357 01	4/15/09	BS	C*PLUMB UNDER SLAB VRU #: 001755318
	4/15/09	DP	no plans at jobsite. \$50 reinspection fee
P357 02	4/16/09	B\$	C*PLUMB UNDER SLAB VRU #: 001756162
	4/16/09	AP	
P351 01	6/10/09	BS	C*PLUMB ROUGH IN TIME: 17:00 VRU #: 001779354
	6/10/09	DA	Plumbing DWV test must have a 10 foot head. 3 foot is only
			allowed for residential aplications
P351 02	6/12/09	BS	C*PLUMB ROUGH IN TIME: 17:00 VRU #: 001780980
	6/12/09	AP	
P357 03	7/07/09	BS	C*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001790807
	7/07/09	AP	T/S: 07/06/2009 01:15 PM JBROCK
			For the addition of the kitchen grese trap drains
P355 01	7/09/09	BS	C*PLUMB SEWER CONNECTION TIME: 17:00 VRU #: 001791953
	7/09/09	AP	T/S: 07/08/2009 01:20 PM JBROCK
			T/S: July 09, 2009 09:57 AM BSUTTON
P353 01	8/05/09	TI	C*PLUMB WATER CONNECTION VRU #: 001804657
	5-5-09	ANS	

----- COMMENTS AND NOTES ------------------

18/U9, 14:U4:53 INSPECTION LICKET PAGE PKB nty INSPECTOR: IVR DATE 8/19/09 ADDRE : 5976 US 401 N SUBDIV: CONTR TOR : PHONE : OWNER. . & : MCDOUGALD JESSIE H & JOELINA G PHONE : PARCEL . . : 08-0655- - -0136- -02-APPL NUMBER: 08-50020908 CP DAYCARE DIRECTIONS: US 401N. NEAR 5920 US 401. 401N TOWARS FUQUAY 4 MI ON RIGHT. T/S: 09/12/2008 01:47 PM VBROWN ----PLEASE CALL CAMERON ADCOCK AFTER YOU DO THE INSPECTION SO THEY CAN CALL THE EL ECTRICAL CONTRACTOR TO COME. 814-7195. STRUCTURE: 000 000 DAYCARE 90PRESCHOOLERS, 35AFT 15EMP FLOOD ZONE . . . : FLOOD ZONE X PROPOSED USE . . . . . . : DAYCARE SEPTIC - EXISTING? . . . : NEW TANK WATER SUPPLY . . . . . . . . COUNTY PERMIT: CTPC 00 CP TEMPORARY POWER CERTIFICATE REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS \_\_\_\_\_\_ E253 01

------ COMMENTS AND NOTES ------

# TEMPORARY POWER CERTIFICATE

					t Contor	
OWNER	Jessie i Joel	na MaDougo	ADDRES	s 59760	CS 401 PHO	NE
LOCAT						
£	ragress Ex	reigy Ti	ne power c	company sl	nall not be r	required to
termina	te electric se	rvice suppli	ed to the pr	emises des	cribed above	on or after
the exp	iration date	specified in	this certific	ate, unless	and until it is	notified in
writing	by the Harn	ett County I	Electrical In	spector to	do so.	
and that I shall	la final inspe	ection is requ with any s	ired before special requ	permanent uirement re	or Temporary power will be equested by t	e approved. the Harnett
Date	8-19-09	}	M	Can	uny Ul	beach
Thisc	ertificate issi	ued pursuan	t to the requ	irements of	Section 105	of the <b>N</b> orth
	10 (E)	*,	- '	and the second s	uance this str	
	orany compi ng building		•	ordinances	of the County	oi narneit
	8.19.09			Bab	Kuth	1
		<del></del>		7	1 000	

PREPARED 9/11/09, 13:59:58 INSPECTION TICKET PAGE INSPECTOR: IVR Harnett County DATE 9/14/09

\_\_\_\_\_

SUBDIV:

CONTRACTOR : PHONE : PHONE : OWNER . . : MCDOUGALD JESSIE H & JOELINA G

PARCEL . . : 08-0655- - -0136- -02-APPL NUMBER: 08~50020908 CP DAYCARE

ADDRESS . : 5976 US 401 N

DIRECTIONS: US 401N. NEAR 5920 US 401. 401N

TOWARS FUQUAY 4 MI ON RIGHT.

T/S: 09/12/2008 01:47 PM VBROWN ----PLEASE CALL CAMERON ADCOCK AFTER YOU DO THE INSPECTION SO THEY CAN CALL THE EL ECTRICAL CONTRACTOR TO COME. 814-7195.

STRUCTURE: 000 000 DAYCARE 90PRESCHOOLERS, 35AFT 15EMP

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE . . . . . : DAYCARE SEPTIC - EXISTING? . . . : NEW TANK

WATER SUPPLY . . . . . . : COUNTY

PERMIT: CPLU 00 CP LAND USE PERMIT

REQUESTED INSP DESCRIPTION

TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

PZ\*ZONING/FINAL INSPECTION TIME: 17:00 VRU #: 001820901 Z820 01 ΤI

DAIAD T/S: 09/11/2009 01:17 PM DJOHNSON ----

------ COMMENTS AND NOTES ------

PREPARED 9/16/09, 9:18:05 INSPECTION TICKET PAGE DATE INSPECTOR: IVR 9/16/09 Harnett County

PHONE :

ADDRESS . : 5976 US 401 N SUBDIV: CONTRACTOR : PHONE :

OWNER . . : MCDOUGALD JESSIE H & JOELINA G

PARCEL . .: 08-0655- - -0136- -02-APPL NUMBER: 08-50020908 CP DAYCARE

DIRECTIONS: US 401N. NEAR 5920 US 401. 401N

TOWARS FUQUAY 4 MI ON RIGHT.

T/S: 09/12/2008 01:47 PM VBROWN ----PLEASE CALL CAMERON ADCOCK AFTER YOU DO THE INSPECTION SO THEY CAN CALL THE EL ECTRICAL CONTRACTOR TO COME. 814-7195.

STRUCTURE: 000 000 DAYCARE 90PRESCHOOLERS, 35AFT 15EMP

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE . . . . . . : DAYCARE SEPTIC - EXISTING? . . . : NEW TANK

WATER SUPPLY . . . . . . : COUNTY

\_\_\_\_\_\_\_

PERMIT: CPLU 00 CP LAND USE PERMIT

REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS 9/14/09 AD PZ\*ZONING/FINAL INSPECTION TIME: 17:00 VRU #: 001820901 Z820 01 9/14/09 DA T/S: 09/11/2009 01:17 PM DJOHNSON ------

PARKING STOPS MUST BE INSTALLED IN ALL PARKING WITHOUT CURBING. DUMPSTER SITE MUST BE SCREENED. HANDICAPPED SPACES MUST BE MARKED AS HANDICAPPED. T/S: 09/14/2009 10:32 AM

1

ADRIGGER -----

9/16/09 PZ\*ZONING/FINAL INSPECTION TIME: 17:00 VRU #: 001822717 T/S: 09/16/2009 09:17 AM NTART --------

## COUNTY OF HARNETT DEPARTMENT OF BUILDING INSPECTION AND PLANNING/DEVELOPMENT CERTIFICATE OF OCCUPANCY

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: Group E Daycare Ceneter	Conditional Use Permit No.: NA
Type of Construction: V	Building Permit No.: 08-50020908
Owner of Building: Robert Naylor	Electrical Permit No.: 08-50020908
Building Address: 5976 US 401 N Fuquay Varina	Insulation Permit No.: 08-50020908
Zoning District: NA	Plumbing Permit No.: 08-50020908
Zoning Permit No.: NA	Mech. Permit No.: 08-50020908
Date: 09-22-09	Envir. C.O. No.: 08-50020908
Brad Sutton	
Building Official	Zoning Official

PREPARED 9/21/09, 13:00:26 INSPECTION Harnett County INSPECTOR: PAGE INSPECTION TICKET INSPECTOR: IVR

ADDRESS . . . 5976 US 401 N SUBDIV-CONTRACTOR: PHONE: OWNER . . : MCDOUGALD JESSIE H & JOELINA G PHONE:

PARCEL . . : 08-0655- - -0136- -02-APPL NUMBER: 08-50020908 CP DAYCARE

DIRECTIONS: US 401N. NEAR 5920 US 401. 401N

TOWARS FUQUAY 4 MI ON RIGHT.

T/S: 09/12/2008 01:47 PM VBROWN ----PLEASE CALL CAMERON ADCOCK AFTER YOU DO THE INSPECTION SO THEY CAN CALL THE EL ECTRICAL CONTRACTOR TO COME. 814-7195.

\_\_\_\_\_\_ PERMIT: CBCO 00 CP BUILDING COMMERCIAL REQUESTED INSP DESCRIPTION TYP/SO RESULT COMPLETED RESULTS/COMMENTS BS C151 01 3/25/09 C\*BLDG FOOTING VRU #: 001747245 compaction test attached 3/25/09 ΑĎ ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001756360 A814 01 4/16/09 TI 4/24/09 AP 5976 US 401 N 4/22/09 BS C\*BLDG SLAB INSP VRU #: 001758495 C159 01 4/22/09 AΡ C153 01 6/10/09 BS C\*BLDG ROUGH IN TIME: 17:00 VRU #: 001779321 DA 6/10/09 brace trusses per truss documents C\*BLDG ROUGH IN TIME: 17:00 VRU #: 001780964 C153 02 6/12/09 BS 6/12/09 ΑP F854 01 9/16/09 TM FM\*FINAL INSPECTION TIME: 17:00 VRU #: 001823426 9/16/09 AP VRU #: 001823434 C179 01 C\*BLDG FINAL TIME: 17:00 9/17/09 IT NTART -----9/16/09 T/S: 09/16/2009 03:34 PM CA T/S: 09/16/2009 03:45 PM NTART -----VRU #: 001824978 C\*BLDG FINAL TIME: 17:00 C179 02TI T/S: 09/21/2009 11:29 AM NTART -----H822 01 9/21/09 GG 9/21/09 ΑP 9/21/09 H824 01 0T 9/21/09 AΡ PERMIT: CPEC 00 CP ELECTRICAL COMMERCIAL INSP DESCRIPTION REQUESTED TYP/SO RESULT COMPLETED RESULTS/COMMENTS

E267 01 4/03/09 BS C\*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 001750801 4/03/09 AΡ E259 01 4/17/09 BS MR. TOMMY WOULD LIKE YOU TO GO AS LATE AFTER LUNCH AS POSSIBLE. \*\*\*\*\*\*\*\*\* 4/17/09 AΡ \*\*\*\*\*\*\*\*\*\*\*\*\* E251 01 6/10/09 BS C\*ELEC ROUGH IN TIME: 17:00 VRU #: 001779339 6/10/09 need electrical change from 3 phase system to single phase DA from engineer to complete electrical inspection. 2. Bond for cold water line must be ahead of shutoff valve

------ ONTINUED ONTO NEXT PAGE

PREPARED 9/21/09, 13:00:26 INSPECTION TICKET PAGE INSPECTOR: IVR DATE 9/21.

nametic county inspection: TVR DATE 9/21/6

ADDRESS : 5976 US 401 N SUBDIV: CONTRACTOR : PHONE : OWNER . : MCDOUGALD JESSIE H & JOELINA G PHONE : PARCEL . : 08-0655- - -0136--02-

APPL NUMBER: 08-50020908 CP DAYCARE

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
E251 02	6/12/09 6/12/09	BS AP	C*ELEC ROUGH IN TIME: 17:00 VRU #: 001780972
E265 01	9/17/09 9/16/09	TI CA	C*ELEC FINAL TIME: 17:00 VRU #: 001823442 T/S: 09/16/2009 03:34 PM NTARTT/S: 09/16/2009 03:45 PM NTART
E265 02	9/21/09	TI AOBC	C*ELEC FINAL TIME: 17:00 VRU #: 001824986 T/S: 09/21/2009 11:29 AM NTART

PERMIT: TYP/SQ	CPMC 00 CP MECHANICA REQUESTED INSP COMPLETED RESULT	DESCRIPTION
M459 01	6/09/09 BS 6/08/09 CA	C*MECH ROUGH IN VRU #: 001779008
M459 02	6/10/09 BS 6/10/09 AE	C*MECH ROUGH IN TIME: 17:00 VRU #: 001779347 need engineers letter on hallway supply duct sourced into 1 boot from 2 different units
M459 03	6/12/09 BS 6/12/09 AP	C*MECH ROUGH IN TIME: 17:00 VRU #: 001780998
M465 01	9/17/09 TI 9/16/09 CA	C*MECH FINAL TIME: 17:00 VRU #: 001823467 T/S: 09/16/2009 03:34 PM NTARTT/S: 09/16/2009 03:45 PM NTART
M465 02	9/21/09 JUSS	C*MECH FINAL TIME: 17:00 VRU #: 001824994 T/S: 09/21/2009 11:29 AM NTART

PERMII:	DEUTIESTED		MMERCIAL DESCRIPTION
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS
P357 01	4/15/09 4/15/09	BS DP	C*PLUMB UNDER SLAB VRU #: 001755318 no plans at jobsite. \$50 reinspection fee
P357 02	4/16/09 4/16/09	BS AP	C*PLUMB UNDER SLAB VRU #: 001756162
P351 01		BS DA	C*PLUMB ROUGH IN TIME: 17:00 VRU #: 001779354 Plumbing DWV test must have a 10 foot head. 3 foot is only
P351 02	.6/12/09 6/12/09	BS	allowed for residential aplications C*PLUMB ROUGH IN TIME: 17:00 VRU #: 001780980
P357 03	7/07/09 7/07/09 7/07/09	AP BS AP	C*PLUMB UNDER SLAB TIME: 17:00 VRU #: 001790807 T/S: 07/06/2009 01:15 PM JBROCK
P355 01	7/09/09 7/09/09	BS AP	For the addition of the kitchen grese trap drains
P353 01	8/05/09 8/05/09	BS AP	T/S: July 09, 2009 09:57 AM BSUTTON
P361 01	9/17/09	ΤÏ	C*PLUMB FINAL TIME: 17:00 VRU #: 001823475

PREPARED 9/21/09, 13:00:26 INSPECTION TICKET INSPECTOR: IVR PAGE DATE Harnett County ADDRESS . . : 5976 US 401 N SUBDIV: CONTRACTOR: PHONE : OWNER . . : MCDOUGALD JESSIE H & JOELINA G PARCEL . . : 08-0655- - -0136- -02-PHONE : APPL NUMBER: 08-50020908 CP DAYCARE \_\_\_\_\_ REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS T/S: 09/16/2009 03:34 PM NTART -----9/16/09 CA P361 02 T/S: 09/21/2009 11:29 AM NTART ---------- COMMENTS AND NOTES -----

DČD	-0304 9)08	١
Rev.	9)08	

Identification	#
County	
Date of Inspec	rtion

#### BUILDING INSPECTORS INSPECTION FORM FOR CHILD CARE CENTERS

NAMI	E OF OPERATION	Lillypade Chi	16 Development	Conter
ADDR	RESS 5976	US 401 NORTH	telephone: 9/	9-567-7433
CITY	Fuguary	US 401 NORTH	STATE N.C.	ZIP 27526
٠٠٠مم	DING INSPECTOR	÷		
1.	to meet the Buildin	ilding that are designated as the licen g Code in effect when an application isted above, to the extent observable, Code?	for licensure is submitted to the	licensing agency he regulating agency.  YesNo
2.	for the safety of the 1)	numbers which do not comply, expla		
	4)	ve violations of a life safety concern?	· · · · · · · · · · · · · · · · · · ·	Yes No j
-	•	uestion numbers		
4.		ed on the violations listed above, do development issue a provisional licens olations?		Yes No
	If yes, how long (3	0-60-90 days) and for which violation	ns?	<del></del>
		ons must be corrected before a licer quivalent protection is documented		ovisional time period is
5.	Number of rooms a (Attach sketch of	pproved for occupancy by children? puilding with rooms identified)	8	· · · · · · · · · · · · · · · · · · ·
5.		oning restriction:		
Signatu	re of Inspector	Rod Sitte	/Date	<u> </u>
lurisdic	tion $M_{23}$	Not Country	/Phone://	1 817-75IS
		d Building Inspection Form is requir	•	

The Inspectors Certificate and Building Inspection Form is required to be completed in its entirety before the Division of Child Development (DCD) can consider the document complete. All questions must be answered; any **NO** answers must have a written explanation.

This form was developed through the cooperation of the Division of Child Development and the Engineering Division of the Department of Insurance. Please note that the inspection forms do not cover all areas of the Code, but are intended to be used as a guide for the local inspector. If additional Code items which are not addressed on these forms are found to be in violation of the Code, please document them on the back of this form.

Prepare in quadruplicate: Original & copy to DCD, 1 copy kept by inspector, 1 copy kept by operator.

Identification #	
County	_
Date of Inspection	_

### CHILD CARE BUILDING INSPECTION FORM

SECT	ION A: The following general questions should be answered for BOTH Educationa	l and Institutio	nal type occu	pancies.
LIGH' 1.	I & VENTILATION  Is the total area of all windows in the child care room equal to or greater than 8% of the floor area or is artificial light provided?		Yes	No
2.a	Does the room have natural ventilation from a minimum amount of operable wind or door area to the outside that would allow a clear opening that is equal to or greater than 4% or more of the floor area?	low	/	
b	(If NO, go to question 2b).  Is space mechanically ventilated as required by North Carolina Mechanical Code?	)	Yes_	No
FIRE	(N/A if an existing building)	N/A	_Yes_	No
3.	Does this building have a manually operated fire alarm system (electrically installed system with pull box stations)?		Yes	No
EXITS				
4.	Are there at least 2 exits (doors, stairs, smoke proof towers, ramps, or horizontal exits) remote from each other on each floor or fire section of the building?		Yes	No
5.	Is the exit capacity adequate?		Yes	No
5.	Are all means of egress adequately illuminated at all times that the building is occupied?		Yes_U	No
7.	Are the means of egress identified by readily visible exit signs when the exit or way to reach it is not immediately obvious to the occupants?		Yes_Co	No
3.	Is emergency power provided for centers with more than 300 occupants or for centers providing night care as required by the Building Code?	N/A_	Yes	No
CORR	IDORS AND ACCESS TO EXITS	-		
),	Are all means of egress unobstructed without passing through a closet, storage area, kitchen, restroom, or other hazardous space?		Yes_	No
0.	Are all exit corridors a minimum 1-hour fire resistance? (If yes, go to Question 12) (N/A applies only if there are no corridors)	N/A	Yes_	No
1.	If corridors are <u>not</u> 1 hour fire rated, do all child care rooms, spaces, and areas have a direct level of discharge exit to the outside?		Yes_L	No
2.	a. Do all corridors, ramps, and passageways have a minimum 6 feet clear width in all areas serving as means of egress for capacity of 100 or more? (N/A if capacity is less than 100)	N/A	Yes Larren	No
	<ul><li>b. Are all corridors, ramps, and passageways not less than 44" clear width in all areas serving as means of egress for capacity of less than 100?</li><li>(N/A if capacity is more than 100)</li></ul>	N/A_L	Yes	No
3.	Are all dead-end corridors no more than 20 feet in length?  (N/A applies only if no dead-end occurs)	N/A_L	Yes	No

14.	Do all doors have a minimum clear opening width of 32" (min. door width of 36")	•		
į	in the following locations:			
	a. between occupied rooms and required exits?		Yes /	No
	b. exit doors leading to the exterior?		Yes	No
15.	Are all doors in the line of exit travel a swinging door (side hinged)?		Yes <u>fare</u>	No
16.	Do doors to rooms that accommodate more than 50 people swing in the direction of travel?	N/A Emma	Yes	No
	(N/A applies if room accommodates less than 50 people)			
17.a	Do all required egress and exit doors have single motion, self-unlocking type handle, lever, push pad, or panic hardware?		Yes English	No
b.	If room accomdates 100 or more people, do all required egress and exit doors have push pads or panic hardware?	N/A <u></u>	Yes	No
STAIR		applicable, al	I questions m	ust be
18.a	Are all stairs serving 50 or more occupants at least 44 inches in width?	N/A śwarz	Yes	No
b	Are all stairs serving less than 50 occupants, at least 36" in width?	N/A	Yes	No
19.	Are all stairs with four or more steps provided with proper handrails			
17.	and guardrails?		Yes	No
20.	Are all interior stairs enclosed with 1-hour rated walls and 1-hour rated "B" labeled doors that are at least 36" wide?		Yes	No
21.	Are the stair enclosure doors self-closing?		Yes	No
WALL	S AND CEILINGS			
22.	a. Are all wall and ceiling coverings throughout building non-combustible? (Use of untreated combustible fiber boards, wood, and other combustible	,	_	
	fiber boards, wood and other combustible finishes is prohibited). b. Do interior wall and ceiling finish materials meet the flame spread ratings		Yes_duran	No
	as required by the Minimum Interior Finish Classification Table, NCBC	•	Yes	No
23.	Do ceilings in habitable rooms have a minimum of 7'-6" clear height?		Yes	No
HEATI	NG SYSTEMS/MECHANICAL		/	
24.	Tis the building free of unvented fuel burning or portable electric space heaters?		Yes L	No
25.	Have air conditioning, ventilation, heating, cooking, and other service			•
	equipment been inspected and approved by the appropriate inspectors?  Date Inspected		Yes	No
	•			
26.	a. Is combustion and ventilation air for boiler or heater rooms taken directly from and discharged to the outside of the building?	N/A	Yes	No
	<ul><li>(N/A if electric heat is installed)</li><li>b. If inside air is used for fuel-burning appliance does it meet the requirements of</li></ul>		•	
	Chapter 7 of the North Carolina Mechanical Code. (N/A if inside air is not used)	N/A	Yes	No
PLUMI	BING			
27.	Does the number of waterclosets and lavatories comply with the Plumbing		_	
	Code as determined by the appropriate inspector? (1 watercloset per 15 children, 1 lavatory per 25 children)		Yes <u>incorrect</u>	No
	Maximum # of persons allowed by plumbing facilities? 150		•	

	<u></u>			
28.	Do the visible and accessible portions of the electrical system comply with applicate sections of the Electrical Code as determined by the appropriate inspector?  Date Inspected	ole .	Yes_com	No
MIVI	ED AND MULTI HEE OCCUPANCIES			
29:	ED AND MULTI-USE OCCUPANCIES  Are all child care areas separated from adjacent occupancies in accordance with			
	the requirement of mixed occupancies and the Occupancy Separation		/	
	Requirements Table? (N/A if no mixed occupancies)	N/A <u></u>	Yes	No
30.	Do all multi-use areas comply with the most restrictive applicable sections of the		_	
	State Building Code for each intended use?	N/A L	Yes	No
	(N/A if no multi-use areas)			
	(Multi-use is defined as an area which will be used for different functions at different times and not concurrent. Example: child care to fellowship hall.)			
ACCI	ESSIBILITY CODES			
31.	Does this building comply with applicable State Building Codes for access/use		,	•
	by persons with disabilities?		Yes_	No
	TION B: The following questions should be answered only for educational occupance of A above.	y in addit	tion to the question	ons answered
32.	Does the building comply with the Allowable Heights and Building Areas Table		,	•
	for Educational Occpancy? (If NO, go to Section C).		Yes_	No
33.	a. Are all rooms, approved for use by children below grade 2, on the		***	
	level of exit discharge? (If NO go to Section C)		Yes L	No
	b. Are rooms used by children in grades 2 and higher no more than one story above	e the		
	level of exit discharge?		Yes Lorenza	No
34.	a. Do rooms used by children who are less than 2 ½ years have a direct exit to the	outside?		
	(N/A applies only if center does not serve children under 2 ½ yrs)	N/A_	Yes	No
	b. Do rooms used by childen under 2 ½ years qualify as alcoves to adjacent spaces	with		
	direct exit to the outside?		Yes_U	No
	c. If the square footage of the child care area is $> 20,000$ square feet, do all rooms	3	p. market	
	for all children have direct exits? (N/A if sq. footage is < 20,000)		N/A 💆 Yes _	No
	(If NO to both a and b or c, go to Section C)			
35:	Are all rooms approved for use by children provided with an operable			
	window which complies with Special Exit Requirements for Educational Occupancy	/?	N/A VYes_	_No
	(N/A if direct exit to outside)			
36.	Is the most remote point in every room occupied by children, including			
	dining room, not more than 200 feet from the nearest exterior exit?	•	Jour Sen	
	(non-sprinklered building)		Yes 📈	No
37	Are smoke detectors provided in the corridors in accordance with			

38. Does the building comply with the Allowable Heights and Building Areas Table for Institutional Occupancy?

Yes\_\_\_\_No\_\_

SECT	Torqe cont		
39:	Are smoke detectors provided in the corridors in accordance with Automatic		
	Fire Detection and NFPA72?	Yes	No
40.	Does the building provide protection from hazardous areas as required by		
3	Special Institutional Occupancies, Group I Unrestrained Occupancies, Protection		
	from Hazardous Areas?	Yes	No
41.	Does the building have an approved automatic sprinkler system in accordance with Special		
	Institutional Occupancies Group I Unrestrained Occupancies?	Yes	No
42.	Is the most remote point in every room occupied by children, including the dining room,		
	not more than 200 feet from the nearest exterior exit?	Yes	No