

VIOLATION NOTICE

3

DO NOT REMOVE!

Harnett County Inspection Department

108 East Front Street • P.O. Box 65

Lillington, NC 27546

Phone: (910) 893-7525 Ext. 1 • Fax: (910) 893-2793

Job Name: _____ Date: _____

Address: _____

Lot No.: _____ Permit No.: _____

(Check Box for Violation)

- | | | | | | | | |
|-------------------------------------|-------------------------------------|----------------------------------|--|-------------------------------------|---------------------------------------|---------------------------------|--------------------------------------|
| <input type="checkbox"/> Footing | <input type="checkbox"/> Foundation | <input type="checkbox"/> Bldg. | <input type="checkbox"/> Elec. | <input type="checkbox"/> Plumb. | <input type="checkbox"/> Mech. | <input type="checkbox"/> Insul. | <input type="checkbox"/> Floor Fram. |
| <input type="checkbox"/> Floor Slab | <input type="checkbox"/> MFG. Home | <input type="checkbox"/> Modular | <input type="checkbox"/> Damp/Water Proof. | <input type="checkbox"/> Structural | <input type="checkbox"/> Wall Sheath. | <input type="checkbox"/> Other | |

Violations Found: _____

24 - Stop stud column RM 119

25 - Repair mid story vent stop RM 119

26 - Engineering required for rt side door relocation and LVE installed

27 - RM 112 Stop stud column.

28 - Truss repairs - BO2A, + 2 ply truss beside it. BO6A, RM-112, CO1GB, RM 104 double truss, RM 105 4 ply truss, RM 124, RM 119, RM 121

Stopped inspection, ran out of time will begin in AM 8/16/19

Code Enforcement Official

Signature: _____ Date: 8/15/19

It is unlawful for any subcontractor, general contractor, or owner to cover or cause to be covered any part of the work with flooring, sheetrock, earth or other material until the proper inspector had ample time to approve the installation