



Professional Service Industries, Inc.

5101 Unicon Drive, Suite E
Wake Forest, NC 27587

Phone:
Fax:

Report No: DFR:0455106-11

Issue No: 1

These test results apply only to the specific locations and materials noted and may not represent any other locations or elevations. This report may not be reproduced, except in full, without written permission by Professional Service Industries, Inc. If a non-compliance appears on this report, to the extent that the reported non-compliance impacts the project, the resolution is outside the PSI scope of engagement.

Approved Signatory: Scott McCune (Department Manager)
Date of Issue: 7/30/2019

Daily Field Report

Client: 814 DEVELOPMENT, LLC
1742 N. CROOKS ROAD
TROY, MI 48084

CC:
DON WEBB, TODD
SCHOLES, TOM
CROUCH

Project: RAINBOW CHLD DEV-SPOUT SPRINGS
SPOUT SPRINGS, NC

Date: 2/2/2019

Technician: Kingsley Esezobor

The undersigned arrived on site, as requested, to observe the placement of concrete for the building slab on grade.

The concrete observed on this date was in compliance with project drawings and specifications. 4 sets of cylinders were cast for compressive strength testing in our laboratory.

Also, the rebar splices that were noted a non-compliant during a previous site inspection visit were corrected and are now in compliance with project drawings.

James P. Slusher, Jr. PE
National Advanced Geophysical
Intertek-PSI

