

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Coggin Homes OWNER: AGENT: PHONE: 919-552-7988
 ADDRESS: 913 RANDELL RD APPLICATION DATE: 4-19-95 DATE EVALUATED: _____
F.V. 29526 PROPOSED FACILITY: 3
 PROPERTY SIZE: 1.3 AC

LOCATION OF SITE: KENNIS CREEK LOT 9
 WATER SUPPLY: On-Site Well Comm. Well Public Other EVAL. METHOD: Auger Boring Pit

PROFILE #	.1940 LANDSCP POS./ SLOPE %	HORIZON DEPTH (IN.)	.1941			
			(M)(1) TEXTURE	(M)(2) STRUCTURE	(M)(3) MINEROLOGY	
1	PS	0-30"	GROUP II SL	GRANULAR	1:1	.1942 WETNESS CONDITION - PS
		30-40"	GROUP III SEL	CRUMB	1:1	.1943, 1936 SAPROLITE - PS
						.1944 RESTRICTIVE HORIZON - PS
						.1948 PROFILE CLASSIFICATION - PS
						PROFILE LTAR - 0.3-0.6
2						.1942 WETNESS CONDITION -
						.1943, 1936 SAPROLITE -
						.1944 RESTRICTIVE HORIZON -
						.1948 PROFILE CLASSIFICATION -
						PROFILE LTAR -
3						.1942 WETNESS CONDITION -
						.1943, 1936 SAPROLITE -
						.1944 RESTRICTIVE HORIZON -
						.1948 PROFILE CLASSIFICATION -
						PROFILE LTAR -
4						.1942 WETNESS CONDITION -
						.1943, 1936 SAPROLITE -
						.1944 RESTRICTIVE HORIZON -
						.1948 PROFILE CLASSIFICATION -
						PROFILE LTAR -
5						.1942 WETNESS CONDITION -
						.1943, 1936 SAPROLITE -
						.1944 RESTRICTIVE HORIZON -
						.1948 PROFILE CLASSIFICATION -
						PROFILE LTAR -

AVAILABLE SPACE (.1945) PS SITE CLASSIFICATION (.1948): _____ SITE LONG-TERM ACCEPTANCE RATE: .5
 OTHER FACTORS (.1946) _____ SYSTEM TYPE SHALLOW CONVENTIONAL
 EVALUATED BY: Ron Dudley OTHER(S) PRESENT: _____
 COMMENTS: _____