HARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH SECTION 307 W. CORNELIUS HARNETT BLVD. LILLINGTON, NC 27546 910-893-7547 PHONE 910-893-9371 FAX

Application for Repair

EMAIL ADDRESS: dry399@gmail.com NAME Dan Young PHONE NUMBER 5184295176 PHYSICAL ADDRESS 82 Ridgecrest Rd Cameron, NC 28326 MAILING ADDRESS (IF DIFFFERENT THAN PHYSICAL) IF RENTING, LEASING, ETC., LIST PROPERTY OWNER NAME Dan Young Starwood -- Unknown Lot # --SUBDIVISION NAME LOT #/TRACT # STATE RD/HWY SIZE OF LOT/TRACT Type of Dwelling: H Modular Mobile Home Stick built HOther. Number of bedrooms _3____ Basement Garage: Yes No Garbage Disposal: Yes No Dishwasher: Yes HNq H Water Supply: | Private Well Community System Directions from Lillington to your site:

In order for Environmental Health to help you with your repair, you will need to comply by completing the following:

- 1. A <u>"surveyed and recorded map"</u> and <u>"deed to your property"</u> must be attached to this application. Please inform us of any wells on the property by showing on your survey map.
- 2. The outlet end of the tank and the distribution box will need to be uncovered and property lines flagged. After the tank is uncovered, property lines flagged, underground utilities marked, and the orange sign has been placed, you will need to call us at 910-893-7547 to confirm that your site is ready for evaluation.

Your system must be repaired within 30 days of issuance of the Improvement Permit or the time set within receipt of a violation letter. (Whichever is applicable.)

By signing below, I certify that all of the above information is correct to the best of my knowledge. False information will result in the denial of the permit. The permit is subject to revocation if the site plan, intended use, or ownership changes.

Jun & Sua		
	01/16/2019	
Signature	Date	

Septic Tank Pumper ____Ricky Nunnery_____

HOMEOWNER INTERVIEW FORM

It is important that you answer the following questions for our inspectors. Please do not leave any blanks if possible, and answer all questions to the best of your ability. Thank You.

Have you received a violation letter for a failing system from our office? HYES [HNO Also, within the last 5 years have you completed an application for repair for this site? HYES [HOO]
Year home was built (or year of septic tank installation) <u>10/6/98</u> Installer of system <u>Wayne Sharp</u>


Designer of System ______

Number of people who live in house?# adults# children# total What is your average estimated daily water usage?gallons/month or day county water. If HCPU please give the name the bill is listed In
3. If you have a garbage disposal, how often is it used? Haily weekly monthly 4. When was the septic tank last pumped? How often do you have it pumped?
5. If you have a dishwasher, how often do you use it? daily every other day weekly
6. If you have a washing machine, how often do you use it? aily every other day weekly monthly
7. Do you have a water softener or treatment system? TYES NO Where does it drain?
8. Do you use an "in tank" toilet bowl sanitizer? YES NO 9. Are you or any member in your household using long term prescription drugs, antibiotics or chemotherapy? YES NO If yes please list
11. Have you put any chemicals (paints, thinners, etc.) down the drain? TYES NO 12. Have you installed any water fixtures since your system has been installed? TYES NO If yes, please list any additions including any spas, whirlpool, sinks, lavatories, bath/showers, toilets
13. Do you have an underground lawn watering system? TYES NO 14. Has any work been done to your structure since the initial move into your home such as, a roof, gutter drains, basement foundation drains, landscaping, etc? If yes, please listn/a
15. Are there any underground utilities on your lot? Please check all that apply:
☐ Power ☐ Phone ☐ Cable ☐ Gas ☑ Water
16. Describe what is happening when you are having problems with your septic system, and when was this first noticed? See attached inspection report.
17. Do you notice the problem as being patterned or linked to a specific event (i.e., wash clothes, neavy rains, and household guests?)

Signature Certificate

Document Ref.: EQVFD-Q2KUE-5CJ3F-K8ME7

Document signed by:



Dan Young

Verified E-mail: dry399@gmail.com

P: 75.140.198.15

Date: 17 Jan 2019 01:53:59 UTC

Im & Sia

Document completed by all parties on: 17 Jan 2019 01:53:59 UTC

Page 1 of 1



Signed with PandaDoc.com

PandaDoc is the document platform that boosts your company's revenue by accelerating the way it transacts.



OPERATIONS PERMIT


Name: (owner) Mike Capers	
Property Location: SR# N/C @87	New Installation Septic Tank
Subdivision Stonwood	Repairs Nitrification Line Lot #
TAX ID#	
11/	Quadrant #
Basement with Plumbing: Garage:	Registration #
Water Supply: Well Public Community	
Distance From Well: 50 ft.	
Following are the specifications for the sewage disposal sys	tem on shove cantioned property
	Ala Alaman Alama
Type of system: Conventional Other	ellow Convertion of
Size of tank: Septic Tank: 1000 gallons Pur	mp Tank: gallons
Subsurface No. of 3 exact length	width of 7 depth of 17
	ditches ft. ditches in.
PERMIT NO. 14455 Date: 1 Inspected by	by: Use Do Environmental Health Specialist
	A 6 corred placed
27 20° 20° 20° 20° 20° 20° 20° 20° 20° 20°	140

HARNE T COUNTY HEALTH DEPARTME

IMPROVEMENT PERMIT

Nº 14455

Be it ordained by the Harnett County Board of Health as follows: Section III, Item B. "No Person shall begin construction of any building at which a septic tank system is to be used for disposal of sewage without first obtaining a written permit from the Harnett County Health Department." Caker New Installation E Septic Tank Property Location: SR# ☐ Repairs Nitrification Line Subdivision I tarwood _ Lot # 6 Tax ID #. _____ Ouadrant #_ Number of Bedrooms Proposed: _ Lot Size:__, 9 Ac Basement with Plumbing: Garage: Water Supply: ☐ Well Public Community Distance From Well: ____ 50 min ft. Following is the minimum specifications for sewage disposal system on above captioned property. Subject to final approval. Type of system: ☐ Conventional Other _ Size of tank: Septic Tank: 1000 gallons Pump Tank: _ ___ gallons Subsurface No. of exact length width of depth of Drainage Field ditches_ of each ditch_ French Drain Required: __ _ Linear feet Date: _ This permit is subject to revocation if site Signed: plans or intended use change. Environmental Health Specialist * Maintain all required * Keep ditch dopH. * Must bring in binches of course 54 40' Ridge cresi Ra





5-15-10/ BY 545

FOR REGISTRATION REGISTER OF DEEDS

***LINERLY SO HARRON P.C.

2012 PRY 15 03:52:53 PM

BK: 2991 PG: 202-204 FEE: \$26:00

NC REV STATP: \$293:00

INSTRUMENT # 2012007780

NORTH CAROLINA GENE	ERAL WARRANTY DEED
Excise Tax: \$293.00	
Parcel Identification No.: 09-9\$66-92-001 1-61 Verified by Harn	ett County
Ву:	
Mail/Box to: Single Source Real Estate Services, Inc., PO Box	87590. Fayetteville, NC 28304
This instrument was prepared by: The Real Estate Law Firm	File No: 30727-12JJ-BMC
Brief description for the Index: 82 Ridgecrest Road, Cameron,	NC 28326
THIS DEED made this 11 hday of May, 2012 by and between	
GRANTOR	GRANTEE
Kenneth Campbell, aka Kenneth W. Campbell and wife Helen Campbell, aka Helen V. Campbell	Daniel Robert Young, Unmarried
- Campbell	
	82 Ridgecrest Road
6250 Wade Stedman Road Wade, NC 28395	Cameron, NC 28326
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	/ /
\ \	100
The designation Grantor and Grantee as used herein shall include include singular, plural, masculine, feminine or neuter as required	e said parties, their heirs, successors, and assigns, and shall
1	
WITNESSETH, that the Grantor, for a valuable consideration acknowledged, has and by these presents does grant, bargain, sell	n paid by the Grantee, the receipt of which is hereby
or parcel of land situated in or near the City of Cameron. Anders	and convey unto the Grantee in fee simple, all that certain lot
more particularly described as follows:	The state of the s
	_3/>
BEING all of Lot Number 61 in a subdivi	sion known as STARWOOD AT
OVERHILLS, PHASE THREE-A and	the same being duly recorded in Plat Cabinet
F, at Slide 706 D, Harnett County Regis	itry, North Carolina
Parcel Identification No. 09-9566-02-001	ua V/~~
Property Address: 82 Ridgecrest Road,	
The property hereinabove described was acquired by Grantor	by instrument recorded in Book 1405Page 978.
All or a portion of the property herein conveyed incl	udes or does not include the primary residence
of the Grantor.	does not include the primary residence
A map showing the above described property is recorded in P	let Cohinet P Stide 705 D
and the second described property is recorded in a	int Cabitlet F Stitle 700 D.

TO HAVE AND TO HOLD the aforesaid lot or parcel of land and all privileges and appurtenances thereto belonging to the And the Grantor covenants with the Grantee, that the Grantor is seized of the premises in fee simple, has the right to convey the same in fee simple, that title is marketable and free and clear of all encumbrances, and that Grantor will warrant and defend the title against the lawful claim of all persons whomsoever, other than the following exceptions: Restrictions, easements and Rights-of-way of Record. Ad-valorem taxes not yet due and payable. IN WITNESS WHEREOF, the Grantor has duly executed the foregoing as of the day and year first written. (SEAL) (Entity Name) By: (SEAL) Title: Helen Campbell By: (SEAL) Title: By: (SEAL) WON THE ANISON OF THE PROPERTY State of North-Carolina County of Cumberland of Notary Public of Cumberland County, State of North Carolina certify that, Kenneth Campbell, aka Kenneth W. Campbell and wife Helen Campbell, aka Helen V. A STANKING S personally appeared before this day and acknowledged the due execution of the BLACK INK foregoing instrument for the purposes therein expressed. Witness my hand and Notarial stamp cal, this 11th day of May, 2012. Commission Expire State of North Carolina County of I, the undersigned Notary Public of Cumberland County, State of North Carolina, certify that USE BLACK INK ONLY personally came before me this day and acknowledged that he is the a North Carolina __corperation/innited / liability company/general partnership/limited partnership (strike through the inapplicable), and that by authority duly given and as the act of each entity, he signed the forgoing instrument in its name on its behalf as its act and deed.

Witness my hand and Notarial stamp or seal this _______ day of ______. My Commission Expires: Notary Public State of North Carolina County-of **BLACK INK ONLY** I, the undersigned Notary Public of Camberland County, State of North Carolina, certify that Witness my hand and Notarial stamp or seal this , day of My Commission Expires: Notary Public The foregoing Certificate(s) of fs/are certified to be correct. This instrument and this certificate are duly registered at the date and time and the Book and Page shown on the first page hereof. Register of Deeds for COUNTY

Question	Response	Details
Approximate total holding capacity:	1000 Gallon	Details
Date of Inspection	1/3/19	
Septic System Location		
Tank Location:	Back Left	
Approximate distance from house or other structur to septic tank (ft):		
Every sanitary sewage treatment and disposal syst distance from the following: Any building foundation	em shall be located at least the	minimum horizontal
Distance from swimming pool, if applicable (ft):	N/A	
Distance from well, if applicable (ft):	N/A	
Septic Tank Location	•	
Media 6 Media 7		
Distance from water lines / property lines unknown.		
Evidence of irrigation within 10 feet any system component?	No	
Evidence of traffic over the septic system:	No	
System appears to be as shown on operations pern rom local Environmental Health Department.	nit Yes	
Septic Tank		
Single Tank or Double Tank?	Single Tank	
approximate total holding capacity:	1,000	
Subsurface wastwater pollution control system perator required?	No	
eptic Tank is accessible.	Yes	
ercentage of solids (sludge and scum) in tank:	10	
ank pumped at time of inspection:	Yes	
id any water return to the tank from the next omponent when the tank was pumped?	No	
ank Structure is in good condition. No strong signs f deterioration or cracks:	No	Cracks in all corners or access lids. Cracks running from outlet lid to baffle lid across tank top.
ank component in need of repair:	Tank Top, Tank top is cracked Lid, Cracks around Outlet Lid lid	I., Cracks around Inlet
afety Hazard?	Yes	
ient, Representative or Property Owner Notified of afety Hazard	Yes	
ccess risers are present:	No	
stance from finished grade to top of tank (in):	3	ese

Question	Response	Details
Both access lids on tank are accessible and were opened during inspection:	Yes	
Tank lids are in tact and in good condition. No strong signs of deterioration or cracks:	No	
Media 1		
Which septic tank lids are in need of repair or replacement?	Outlet	
Reason for repair / replacement:	Deteriorated	
Baffle is in tact and in good condition:	No	Crack in baffle wall
Media 2		
Water level in tank relative to tank outlet:	Yes	
Water level in tank is below the invert of the inlet.	Yes, Water level is below the inle	et.
Signs of root intrusion in tank:	No	
Evidence of tank leakage.	No	
Outlet Tee / Baffle	· · · · · · · · · · · · · · · · · · ·	
Outlet Tee / baffle is present:	Yes	
Outlet baffle / tee is constructed of:	PVC Built	
Outlet tee is in good condition. No strong signs of deterioration.	N/A	
Outlet tee is at an appropriate height relative to the inlet.	Yes	
Filter is present in outlet tee:	No	
The requirement(s) for an effluent filter and access dev Construction Authorization is issued on or after Januar require this component be brought up to code in the e repair is requested. (Ref. NCAC .1952)	ry 1, 1999. The Environmental He	alth Department may
Connection present from tank to next component:	Yes	
Does the system have a pump and pump tank?	No	
Distribution device present:	Yes	
Distribution Device		
Distribution device is accessible:	Yes	
Distribution Device Location		
Media 8		

Distribution Box

Type of distribution device:

Question	Response	Details
Size of Distribution Box	Small	Details
Distribution device is providing equal distribution	Yes	
of effluent.	165	
Presence of roots in distribution device.	No	
Distribution device appears to be watertight:	No	
Corrosion / deterioration present in distribution device:	Severe Deterioration	Distribution box lid completely deteriorated and box is crumbling. Box packed full of dirt when excavated. Cleaned out box and all lines too water
Media 9 Media 10		
Confirmation that system effluent is reaching the drain field from the distribution device:	Yes	
Conditions present that have prevented or hindered the inspection of the distribution device.	No	
Drain Field		•
Drain Field Location		
Media 11 Media 12 Media 13 Media 14 Media 15		
Method for dosing to the field.	Gravity	
Configuration for dispersal in the field:	Parallel Trench	
Nature of media:	Gravel	
Evidence of past or current surfacing at time of inspection:	Yes	End of lateral furthest from house
Media 3 Media 4		
Evidence of surface water inflow:	No	T
Adequate ground cover over drain field (6" or more):	No	Two bottom laterals are very shallow and do not have adequate ground cover.

Question	Response	Details
Objects or structures that may affect the condition of the system or system components:	Yes	Fire pit dug over top of lateral closest to house allowing for pooling and surface water inflow.
		•



Media 5

Leach lines probed:	Yes
System effluent is reaching the leach field:	Yes
Soil Condition at Leach Lines:	Top two laterals are normal. Bottom lateral that is surfacing is hypersaturated
Number of leach lines:	3
Vegetation, grading and drainage noted that may affect the condition of the system or system components.	No
Additional Information	

Media



Media 1



Media 2



Media 3



Media 4



Media 5



Media 7



Media 6



Media 8



Media 9



Media 10





Media 11 Media 12



Media 13



Media 14



Media 15



Onsite Wastewater System Inspection

Audit Title

82 Ridgecrest

Conducted on

1/3/19

Location

82 Ridgecrest Rd Cameron, NC 28326 United States (35.25742675744313, -79.02470849278349)

Prepared by

Marlin

Completed on

1/3/19, 1:46 PM

Disclaimer

No representation, warranties or opinions are hereby given, written or expressed otherwise, as to the future performance of onsite wastewater system described herein. This onsite wastewater system inspection is a presentation of system facts in place on date of inspection. The inspectors do not accept responsibility for any consequences arising from the use of the information herein. The report is based on matters which were observed or came to the attention of the inspectors during the day of the inspection and should not be relied upon as an exhaustive record of all possible issues that may exist or potential improvements that can be made.

Confidentiality Statement

In order to maintain the integrity and credibility of the inspection processes and to protect the parties involved, it is understood that the the inspectors will not divulge to unauthorized persons any information obtained during this inspection unless legally obligated to do so. Unless otherwise specified, Marlin will only discuss the results of this inspection with the buyer, seller and their respective representatives.

82 Ridgecrest