

February 19th, 2019

Cynthia Deloris McKoy
4195 McNeill Rd
Sanford, NC 27332

RE: Septic System Application for Repair

Dear Ms. McKoy,

An attempt was made to evaluate your property for the purpose of issuing a Repair Permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Uncover outlet lid on septic tank and break seal.
- 2. Have system pumped out
- 3. Replace sanitary T
- 4. Other – **Septic distribution box shall be uncovered. Water line shall be located and displayed between well and house. House power access shall be marked onsite.**

Your application will be put on hold until the selected items above have been addressed. When completed **call 893-7547 to confirm** that the items mentioned have been corrected, we will then reschedule your property for evaluation.

Sincerely,



Andrew Currin, R.E.H.S.
Environmental Health Specialist
Harnett County Department of Public Health

AC/kh
Copy - Central Permitting