

May 16th, 2019

Gail Brafford
7431 Hwy 87 S
Sanford, NC 27332

RE: Septic System Application for Repair: 36 Gabby and 84 Gabby Lane

Dear Mrs. Brafford,

An attempt was made to evaluate your property for the purpose of issuing a Repair Permit. The evaluation could not be completed for one or more of the following reasons.

___ 1. Uncover outlet lid on septic tank and break seal.

___ 2. Have system pumped out

___ 3. Replace sanitary T

X 4. Other – Maintenance recommended of system prior to repair. Outlet end of tank shall be uncovered and verified sanitary tee intact. Supply line shall be verified as clear of any obstructions. D-Box shall be uncovered and inspected (if applicable). Drain lines shall be snaked and verified of any potential obstructions. Reconfirm with EH when ready and/or if problem persist post-maintenance,

If you have any questions I can be reached at 910-893-7547 between 8-9 am.

Sincerely,



Andrew Currin, R.E.H.S.
Environmental Health Specialist
Harnett County Department of Public Health

AC/kh

Copy - Central Permitting