Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Description

System Type(s) Site LTAR

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Location Water Evalua	ss: sed Facility:	015KK 1: X Auge	Whick Prope	Evaluated: 480 (20 Flow (.1949): 2 erty Recorded: ndividual	Well Spring		her		
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Consistence		OTHER PROFILE FACTORS .1942 Soil .1943 .1956 .1944				Profile
	Бюре 70	(111.)	Texture	Mineralogy	Wetness/ Color	Soil Depth (IN.)	Sapro Class	Restr Horiz	Class & LTAR
1,2	L 25%.	0-48	GR SL	VIFE SEXP	usub	48"			5.6
		7-4		997 F.X			231 M2 8 8 8 8		
							20 2 V		
								v.	
						,			
Descript Available System T Site LTA	e Space (.1945 Type(s)	Sy	stem Rep	pair System Si	Other Factors (.1946): te Classification (.1948): Evaluated By: Others Present:	intabl Britani	e j Adaw	15	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	<u>TEXTURES</u>	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET	
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY	
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	П	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC	
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC	

0.4 - 0.1

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY C-CLAY SC-SANDY CLAY

EXPANSIVE

IV

