HTE # or Last Name EH 2006-0024

523 RAWLS CHURCH RD.

Malfunctioning Systems Fill out this section at the time the Malfunction is Evaluated and a Permit issued or other Remedy Proposed.									
For the system that malfunctioned or was damaged or destroyed.									Replacement System or Remedy Code
Unique Identifier - REQUIRED	Failing System Code	Age (whole number)	Was it Initial or Repair	Type Distribution	LTAR today	Design Flow (gpd)	Type of Failure Code	Primary Cause Code	
EH2006-0024	GTR	57	I	GS	NA	360	SW	T	TANK