HTE # or Last Name GH ~~2012~~ 2101-0004 Santiago Aguilar

Malfunctioning Systems

Fill out this section at the time the Malfunction is Evaluated and a Permit issued or other Remedy Proposed.

For the system that malfunctioned or was damaged or destroyed.									Replacement System or Remedy Code
Unique Identifier - REQUIRED	Failing System Code	Age (whole number)	Was it Initial or Repair	Type Distribution	LTAR today	Design Flow (gpd)	Type of Failure Code	Primary Cause Code	
Santiago Aguilar (131 Green Spring)	GTR	23	I	DBox		360	Tank	A	Tank