Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Applicant:

Owner:

Address:

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Date Evaluated:

Locati Water Evalua	sed Facility: on of Site: Supply: ation Method of Wastewate		Proper Public Inc	n Flow (.1949): ty Recorded: dividual	☐ Cut	e:	ner	_	
P R O F I	.1940		SOIL MORPHOLOGY		OTHER PROFILE FACTORS				
L E #	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1-2	2-5%	0-6	LS(A) Gr LS G- SII SBK		104/26/2041"		_	_	PS.5 Group TIT
		6-34	LS G-		*				
		34-48	Sil sak						
			17						
		-							

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
Available Space (.1945)			Evaluated By: Mahamatan
System Type(s)		25 % rud	Others Present:
Site LTAR		. 5	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	<u>WET</u>
R-RIDGE	I	S-SAND	1.2 - 0.8		
S-SHOULDER SLOPE	_	LS-LOAMY SAND		VFR-VERY FRIABLE	NS-NON-STICKY
L-LINEAR SLOPE				FR-FRIABLE	SS-SLIGHTY STICKY
FS-FOOT SLOPE	П	SL-SANDY LOAM	0.8 - 0.6	FI-FIRM	S-STICKY
N-NOSE SLOPE		L-LOAM		VFI-VERY FIRM	VS-VERY STICKY
H-HEAD SLOPE				EFI-EXTREMELY FIRM	NP-NON-PLASTIC
CC-CONCLAVE SLOPE	Ш	SI-SILT	0.6 - 0.3		SP-SLIGHTLY STICKY
CV-CONVEX SLOPE		SIL-SILT LOAM			P-PLASTIC
T-TERRACE		CL-CLAY LOAM			VP-VERY PLASTIC
FP-FLOOD PLAN		SCL-SANDY CLAY LOAM			

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY SC-SANDY CLAY

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

PR-PRISMATIC Show profile locations and other site features (dimensions, references or benchmark, and North) 110 45 (2) 3 Br Kellam Dr