Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Anderso Applicant: MHP LLC Address: 51 S. Paggy ST. Proposed Facility: (2) SwmH Date Evaluated: Date Evaluated:
Design Flow (.1949): 720 GPD Property Size: Location of Site: Property Recorded: Water Supply: Public Individual ☐ Spring Other ☐ Well Evaluation Method: Auger Boring Pit Industrial Process ☐ Cut Sewage ☐ Mixed Type of Wastewater:

P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
l	L	0-6	15		> 48"	>48"	_	_	5.6
	L 5.78	6-48	SL						
2	L	0.8	45		>48"	>48 "		_	5.6
	L 5.7%	8-48	SZ				-		
							1		
							e e		

Description	Initial	Repair System	Other Factors (.1946):
	System	_	Site Classification (.1948):
Available Space (.1945)			Evaluated By: M REHS
System Type(s)			Others Present:
Site LTAR		. 6	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY 0.4 - 0.1

EXPANSIVE

C-CLAY SC-SANDY CLAY

GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

IV

