Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Ken Williams	olicant:	to Evolveted 9-29-27		
Address: 21574 NC Proposed Facility: 21	BrsFD De	te Evaluated: 9-29-27 sign Flow (.1949): 2406D	Property Size:	
Location of Site: Water Supply:	Pro Public	pperty Recorded:	Spring	Other
Evaluation Method: Type of Wastewater:	Auger Boring Sewage	☐ Pit ☐ Cut ☐ Industrial Process	Mixed	

P R O F I .1940		SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS					
L E #	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,2	L	0-20	LS G-	Folus / we/war	104R7/1	>c18"	_	_	PS. 4
	5-7%	20-118	sci szk	Filsslselsxe	10y27/1 241"				Grou
	2								
				*					
									7
							-		

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)			Evaluated By: W///
System Type(s)		25 Tored	Others Present:
Site LTAR		.4	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
H-HEAD SLOPE CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3	EFFEATREMELT FIRM	SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

0.4 - 0.1

STRUCTURE SG-SINGLE GRAIN M- MASSIVE

CR-CRUMB **GR-GRANULAR**

SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY


PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY C-CLAY SC-SANDY CLAY

EXPANSIVE

IV



NC 24-27