Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Owner:

Address:

Proposed Facility:

Location of Site:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

System

Available Space (.1945) System Type(s)

Site LTAR

Applicant: TArrisen Mcloy

Date Evaluated: 12-15-22

Design Flow (.1949): 360

Property Recorded:

Sheet: Property ID:

Lot #:

File #: Code:

Property Size:

FH 2212-0002 979 Brichwill 12D

Evalua Type o	Supply: tion Method of Wastewate	Auge	Public Pr Boring Sewage	Individual W	☐ Cut		er		
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,2	L	0-10	<u>x</u>	FR GARSHIP	VI.				
		10-310	SUAY	on AMN SP.	24 29"				.4-,3
Descrip	ption	I	nitial R	tepair System	Other Factors (.1946):				

Site Classification (.1948): V-125

Others Present:

Evaluated By:

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE	NS-NON-STICKY
L-LINEAR SLOPE				FR-FRIABLE	SS-SLIGHTY STICKY
FS-FOOT SLOPE	II	SL-SANDY LOAM	0.8 - 0.6	FI-FIRM	S-STICKY
N-NOSE SLOPE H-HEAD SLOPE		L-LOAM		VFI-VERY FIRM EFI-EXTREMELY FIRM	VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE	III	SI-SILT	0.6 - 0.3	EFI-EXTREMELT FIRM	SP-SLIGHTLY STICKY
CV-CONVEX SLOPE		SIL-SILT LOAM			P-PLASTIC
T-TERRACE		CL-CLAY LOAM			VP-VERY PLASTIC
FP-FLOOD PLAN		SCL-SANDY CLAY LOAM			

IVSIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

