Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for, ON-SITE WASTEWATER SYSTEM

John	TIOTE WITTER	I D I LIVI			
Owner: Coots Applic	ant:	0	10-27		
Address: 970 Crukeries	いしか Date	Evaluated: 🕻	5-9-23 49): 480GPD		
Proposed Facility: 5FF	Desig	n Flow (.194	49): 48001	Property Size:	
Location of Site:	Prope	rty Recorded	d:		
Water Supply:	☐ Public☐ Ir	ndividual	Well	☐ Spring	Other
Evaluation Method: Au	iger Boring	☐ Pit		Cut	
Type of Wastewater:		☐ Indi	ustrial Process	☐ Mixed	

L La E Po	.1940		SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	1	0-48	45 Gr	Folishelika	×48"	>48"		_	5.8
	2-5%								S.8 Group
						P.			
						s. l			
	3.5			1				1 2	
							7.9		
					X				
				-					

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)			Evaluated By: MAREH
System Type(s)		~	Others Present:
Site LTAR		.8	A.T.

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

