Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: J. (664) Applicant:	
Owner: J. Coal Applicant: Address: 970 Creck view Date Evaluated:	
Proposed Facility: SFD Design Flow (.1949): Property Size:	
Location of Site: Property Recorded:	
Water Supply: Deblic Individual Well Spring Other	
Evaluation Method Auger Boring Pit Cut	
Type of Wastewater: Sewage Industrial Process Mixed	

P R O F I	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		PR			
L E #			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	Sapro R	944 Profile estr Class oriz & LTAR
ţ	1	0-28	LS Gr	Fo/no/ne/nap	798"	> 48°		S.6 Group
	2-5%	28-48	SL Gr	Folisheline				777
					di v			
			- 7					
				1				
				1				
	X 5 5 6					-		

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)		-	Evaluated By:
System Type(s)			Others Present: M RCHs
Site LTAR		. 6	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE	I	S-SAND	1.2 - 0.8		
S-SHOULDER SLOPE		LS-LOAMY SAND		VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY ' SS-SLIGHTY STICKY
L-LINEAR SLOPE FS-FOOT SLOPE	II	SL-SANDY LOAM	0.8 - 0.6	FI-FIRM	S-STICKY
N-NOSE SLOPE		L-LOAM		VFI-VERY FIRM EFI-EXTREMELY FIRM	VS-VERY STICKY NP-NON-PLASTIC
H-HEAD SLOPE CC-CONCLAVE SLOPE	Ш	SI-SILT	0.6 - 0.3	EFI-EATREMELT FIRM	SP-SLIGHTLY STICKY
CV-CONVEX SLOPE		SIL-SILT LOAM			P-PLASTIC
T-TERRACE FP-FLOOD PLAN		CL-CLAY LOAM SCL-SANDY CLAY LOAM			VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

