Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

SOIL/SITE EVALU for ON-SITE WASTEWATE		Code:	8-28.2)		
Proposed Facility: Oxhour	Date Evaluated: \$-28-23 Design Flow (.1949): 3606PP Property Recorded: Individual Well Pit Cut e Industrial Process	Property Size:  Spring  Mixed	Other Other		

R O	.1940		SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
E #	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
, 2	1	0-26	15 Gr	f-/nsp/nxe	248"	>48"	_	_	5.6 Grout
	5-7%	26-48	SL Gr	Folnsplaxe					Group
				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
						1.	200		
	)					-			

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)			Evaluated By: M & REH
System Type(s)		-	Others Present:
Site LTAR		. 6	A.T.

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	<b>GROUP</b>	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE	NS-NON-STICKY
L-LINEAR SLOPE FS-FOOT SLOPE N-NOSE SLOPE	П	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FR-FRIABLE FI-FIRM VFI-VERY FIRM	SS-SLIGHTY STICKY S-STICKY VS-VERY STICKY
H-HEAD SLOPE			21211212	EFI-EXTREMELY FIRM	NP-NON-PLASTIC
CC-CONCLAVE SLOPE	III	SI-SILT SIL-SILT LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC
CV-CONVEX SLOPE T-TERRACE		CL-CLAY LOAM			VP-VERY PLASTIC
FP-FLOOD PLAN		SCL-SANDY CLAY LOAM			

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

MINERALOGY SLIGHTLY EXPANSIVE

**EXPANSIVE** 

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY
DR PRISMATIC

PR-PRISMATIC Show profile locations and other site features (dimensions, references or benchmark, and North) 100