Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Description

System Type(s) Site LTAR

Available Space (.1945)

Initial

System

Repair System

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Location Water Evalua		: Auge	Date l Desig Prope ☐ Public ☐ Ir	Evaluated: n Flow (.1949): rty Recorded: ndividual	☐ Cut	ze:	er		
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (ln.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,2	L32	0-5	グレ	FREADON	34-36				
	_	5-42	ELAY	Fm 88450	34-36				. 3
									-
					(A				

Other Factors (.1946):

Site Classification (.1948): P3

Others Present:

Evaluated By: 72

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET	
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8 VFR-VERY FRIABLE FR-FRIABLE		NS-NON-STICKY SS-SLIGHTY STICKY	
FS-FOOT SLOPE N-NOSE SLOPE	П	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC	
H-HEAD SLOPE CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3	EFF-EATREWIELT FIRM		
	IV	SIC-SILTY CLAY C-CLAY SC-SANDY CLAY	0.4 - 0.1			
STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY	١, ٨	MINERALOGY SLIGHTLY EXPANSIVE EXPANSIVE	Dim.			
PL-PLATY PR-PRISMATIC	Show profi	le locations and other site feature	es (dimensions, refe	rences or benchmark, and North)		
	0		18	2		
			18			
	New					
	X					
	10	(50)				
Way of	145.					
1 Magic	PRÁTI	Any.				