Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Applicant: Ronald John Brekey Owner: Date Evaluated: 4-26-24 Design Flow (.1949): 360 Pro Address: Proposed Facility: Go SGD Property Size: Location of Site: Property Recorded: Public Individual ☐ Spring Other Water Supply: Evaluation Method: Auger Boring ☐ Pit ☐ Cut Sewage Type of Wastewater: ☐ Industrial Process Mixed

P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (ln.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1, 2	L 5-86	0-18	×	FR. GRUND					
		18-36	EL	Fru sous.P.	34-36" ZI	c			.35
2	L-5-6%	0-12	SL.	K GLN3NN					
		12-34	SLL	Fan Signs. P.	30° 21				٠5
								1	

Description	Initial System	Repair System
Available Space (.1945)		
System Type(s)		25%
Site LTAR		63

Other Factors (.1946): Site Classification (.1948): Evaluated By: Others Present: COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE	1 -	S-SAND	1.2 - 0.8		
S-SHOULDER SLOPE	1	LS-LOAMY SAND	1.2 - 0.6	VFR-VERY FRIABLE	NS-NON-STICKY
L-LINEAR SLOPE				FR-FRIABLE	SS-SLIGHTY STICKY
FS-FOOT SLOPE	II	SL-SANDY LOAM	0.8 - 0.6	FI-FIRM	S-STICKY
N-NOSE SLOPE		L-LOAM		VFI-VERY FIRM	VS-VERY STICKY
H-HEAD SLOPE			23.05	EFI-EXTREMELY FIRM	NP-NON-PLASTIC
CC-CONCLAVE SLOPE	III	SI-SILT	0.6 - 0.3		SP-SLIGHTLY STICKY
CV-CONVEX SLOPE		SIL-SILT LOAM			P-PLASTIC
T-TERRACE		CL-CLAY LOAM			VP-VERY PLASTIC
FP-FLOOD PLAN		SCL-SANDY CLAY LOAM			

IVSIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

