

October 4th, 2024

Mair M Gillis
90 Barnsley Rd
Angier, NC 27501

RE: Existing Tank Application #EH2409-0012

To whom it may concern

An attempt was made to evaluate the above property for issuing an existing tank permit. The evaluation could not be completed for one or more of the following reasons.

___ 1. Uncover outlet lid on septic tank fully and break seal. (\$25.00 fee incurred).

___ 2. Have system pumped out

___ 3. Need site plan

X 4. Other – Survey Map must be provided as site plan, GIS map is not adequate. Property survey corner irons must be uncovered and demonstrated. Property lines need to be marked every 50' between survey irons. Have a septic contractor to locate and demonstrate/flag the septic system drain field from start to end.

Your application will be put on hold until the selected items above have been addressed. When completed **call 893-7525 to confirm** that the items mentioned have been corrected we will then reschedule your property for evaluation.

Sincerely,



Reynold Levocz, R.E.H.S.
Environmental Health Specialist
Harnett County Department of Public Health

RL/kh

Copy - Central Permitting