## HARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH SECTION 307 W. CORNELIUS HARNETT BLVD. LILLINGTON, NC 27546 910-893-7547 PHONE 910-893-9371 FAX

# **Application for Repair**

		1 dearl @ Ano	-0011
The Dondo		PRESS: LINDSY @ ANG	MITHUI. COM
OWNER NAME FTOY PYONO E	KUTY MOLOTY	PHONE 910- 158-	10752 Lynn miltor
PHYSICAL ADDRESS 532 JOB CL	alling Road. Lilling	gton NC 275	46
MAILING ADDRESS (IF DIFFFERENT THAN PI	PHYSICAL) SOME OF Ph	usical above	
IF RENTING, LEASING, ETC., LIST PROPERTY	OWNER NAME NAME	N. L. C.	
SUBDIVISION NAME	LOT #/TRACT # STATE	ST HIGHWAY S Y(1 N) ERD/HWY	1.00 +1- OCTUS SIZE OF LOT/TRACT
Type of Dwelling: [] Modular [] Mo	obile Home ( Stick built	[] Other	
Number of bedrooms 3 [] Base	ement		
Garage: Yes № No []	Dishwasher: Yes No []	Garbage [	Disposal: Yes [] No
Water Supply: [] Private Well	[] Community System	County	
Directions from Lillington to your site:	From W Front Str	ed head wes	ton
Huy 421 N toward	Samford. Go app	rox 3.5 miles	
Turn right onto	TOE Caling Road.	Property ap	prox .5 mile
	ſ	in the right	
<ol> <li>In order for Environmental Health to he.</li> <li>A "surveyed and recorded map" an wells on the property by showing of</li> <li>The outlet end of the tank and the concept of the</li></ol>	nd <u>"deed to your property</u> " must be on your survey map.	attached to this application.	Please inform us of any gged. After the tank is
us at 910-893-7547 to confirm that Your system must be repaired within 30 day letter. (Whichever is applicable.)	t your site is ready for evaluation.		
By signing below, I certify that all of the about the denial of the permit. The permit is subject to the denial of the permit is subject to the pe			
Ja Per	5/	21/2025	
Owner Signature		Date	

#### HOMEOWNER INTERVIEW FORM

It is important that you answer the following questions for our inspectors. Please do not leave any blanks if possible, and answer all questions to the best of your ability. Thank You.

Have you received a violation letter for a failing system from our office? [] YES [ NO Also, within the last 5 years have you completed an application for repair for this site? [] YES [ NO
Year home was built (or year of septic tank installation) home built in 1013 Installer of system Septic Tank Pumper Multiples Stylics Designer of System
1. Number of people who live in house? # adults # children 5 # total  2. What is your average estimated daily water usage? Why water. If HCPU please give the name the bill is listed in FW Proposition.
<ol> <li>If you have a garbage disposal, how often is it used? [ ] daily [ ] weekly [ ] monthly N H</li> <li>When was the septic tank last pumped? 5 6 5 6 5 How often do you have it pumped? Nerv 10 10 10 10 10 10 10 10 10 10 10 10 10</li></ol>
11. Have you put any chemicals (paints, thinners, etc.) down the drain? [ ] YES [X] NO  12. Have you installed any water fixtures since your system has been installed? [ ] YES [X] NO If yes, please list any additions including any spas, whirlpool, sinks, lavatories, bath/showers, toilets
13. Do you have an underground lawn watering system? [ ] YES [X] NO  14. Has any work been done to your structure since the initial move into your home such as, a roof, gutter drains, basement foundation drains, landscaping, etc? If yes, please list (OO) (CO) (OO)  15. Are there any underground utilities on your lot? Please check all that apply:  [ ] Power [ ] Phone [X] Cable [ ] Gas [ ] Water
16. Describe what is happening when you are having problems with your septic system, and when was this first noticed?  1000 1000 1000 1000 1000 1000 1000 10
17. Do you notice the problem as being patterned or linked to a specific event (i.e., wash clothes, heavy rains, and household guests?) [ ] YES [) NO If Yes, please list_



#### **Certificate Of Completion**

Envelope Id: 335AE128-C8D8-426A-B174-B9C7AE29FC2E

Subject: Complete with Docusign: Application For Repair.pdf

Source Envelope:

Document Pages: 2 Certificate Pages: 4

Signatures: 1 Initials: 1

AutoNav: Enabled

Envelopeld Stamping: Enabled

Time Zone: (UTC-08:00) Pacific Time (US & Canada)

Status: Completed

Envelope Originator:

Ann C. Milton 3183 US 421 N 3183 US 421 N

Lillington, NC 27546

ann@annmilton.com

IP Address: 2600:6c9f:900:d

#### **Record Tracking**

Status: Original

5/21/2025 12:42:46 PM

Holder: Ann C. Milton ann@annmilton.com Location: DocuSign

# Signer Events

Signing Complete

**Payment Events** 

Completed

Flor Prado

prado7907@gmail.com

Security Level: Email, Account Authentication

(None)

Signature

Signed using mobile

Security Checked

Security Checked

Status

Je Per

Signature Adoption: Drawn on Device Using IP Address: 64.98.126.114

Timestamp

Sent: 5/21/2025 12:44:23 PM Viewed: 5/21/2025 12:46:51 PM Signed: 5/21/2025 12:48:27 PM

5/21/2025 12:48:27 PM

5/21/2025 12:48:27 PM

**Timestamps** 

Electronic Record and Signature Disclosure:

Accepted: 5/21/2025 12:46:50 PM

ID: baf822f8-ec77-40a1-af8a-cd8264a2838e

In Person Signer Events	Signature	Timestamp	
Editor Delivery Events	Status	Timestamp	
Agent Delivery Events	Status	Timestamp	
Intermediary Delivery Events	Status	Timestamp	
Certified Delivery Events	Status	Timestamp	
Carbon Copy Events	Status	Timestamp	
Witness Events	Signature	Timestamp	
Notary Events	Signature	Timestamp	
Envelope Summary Events	Status	Timestamps	
Envelope Sent Certified Delivered	Hashed/Encrypted Security Checked	5/21/2025 12:44:23 PM 5/21/2025 12:46:51 PM	

Electronic Record and Signature Disclosure

#### MAPLES SEPTIC TANK SERVICE, INC.

#### 80 Thomas Kelly Road

#### Sanford, NC 27330

# (919) 258-3750 Phone (919) 258-3914 Fax

### Inspection Certification #24751

No representation, warranties, or opinions are hereby given, written or expressed otherwise, as to the future performance of onsite wastewater system described herein. This onsite wastewater system inspection is a presentation of system facts on date of inspection.

Address of Property 537 Joe Collins Bd
Current Owner on Record
Inspection Requested by Dawn Hickman
Other Name
Company/Contact Number Ann Milton 910-814-1012
Date of Inspection 5/5/25
Copy of Operations permit from County of Environmental Health attached.  Operations Permit not available.
Type of water supplyWellPublic WaterCommunity Water
Location of Septic Tank and Septic Tank details:
ft from well if applicable
ft from water line if applicable
Approximate distance from surface to top of tank
Access riser(s )
Tank lids intactyesno
Tank has baffle wall
Inflow to tank is noted as sufficient
Inflow to tank is noted as insufficient or blocked
Outlet has a filteryes no unknown
Outlet T is present
Effulent leaves the outletyesnounkown
Roots present in tank

Evidence of infiltration into tank of surface wateryesno
Evidence of tank leakage noted
Unable to locate tank. System inspection cannot be completed until tank is located
Garbage Disposalyesnounknown
Number of bedrooms
Date tank was last pumped 5/5/25
Percentage of sludge detected in tank%
Does System have a pump tank?yes (complete blanks below)no
ft from house or structure
ft from well if applicable
ft from water line if applicable
ft from property line
Approximate distance from surface to top of tank
Access riser(s) in placeyesno
ft from Septic tank
Location of control Panel
Electrical connection are in place and properly grounded
Alarm is working properly
Pump is working properly
Dosing volume correct
Unable to operate pump/alarm due to lack of electricity at site at time of inspection
System requires a subsurface operatoryesno
If yes, Operator Name Contact Number
Copy of most recent operator report attachedyesno
Drain field located:
10_ft from property line
ft from septic/pump tank
# of lines located
§ D ft length of system
Type of system:ConventionalInnovativeExperimentalControlled Demo
Pretreatment: Type of Pretreatment

Brief Description of System Type: Terra Cotta
Evidence of past or current surfacing at time of inspection  Large trees or other vegetation noted over drain field area, if YES briefly describe
Evidence of traffic over drain field, if YES briefly describe
Other pertinent facts noted during inspection Tank is an old howevede tanks. Water that was put down the lines came
back into the take so the lines are not
taking. The water that is getting down the lines
is coming up into the Yard at the end of the line.
Inspector Name: Maples Septic Tank Services, INC. Owner Terry R. Maples Certification #24751
80 Thomas Kelly Road, Sanford NC 27330 Office phone (919) 258-3750 Cell (919) 356-5785
Inspectors Signature: Date: 5/8/25

HARNETT COUNTY TAX ID# 13.0030.0076 FOR REGISTRATION
Kimberly S. Hargrove
REGISTER OF DEEDS
Harnett County No.
2013 NOV 27 03:04:39 PM
BK:3175 PG:947-948
FE:\$26.00
INSTRUMENT # 2013019213



Excise Tax

Recording Time, Book and Page

Mail after recording to Bain, Buzzard & McRae, LLP, Attorneys at Law, 65 Bain St., Lillington, NC 27546 This instrument prepared by Bain, Buzzard & McRae, LLP, Attorneys at Law, 65 Bain St., Lillington, NC 27546

Brief Description for the index: Lot 2/1.06 acre

#### NORTH CAROLINA GENERAL WARRANTY DEED

THIS DEED made this | 3 day of November, 2013 by and between

GRANTOR

GRANTEE

Rose K. Crowder, unmarried

532 Joe Collins Road Lillington, NC 27546 Flor Antonio Prado and wife, Kelly Renae Mabry 532 Joe Collins Road Lillington, NC 27546

Enter in appropriate block for each party: name, address, and, if appropriate, character of entity, e.g., corporation or partnership.

The designation Grantor and Grantee as used herein shall include said parties, their heirs, successors, and assigns, and shall include singular, plural, masculine, feminine or neuter as required by context.

WITNESSETH, that the Grantor, for a valuable consideration paid by the Grantee, the receipt of which is hereby acknowledged, has and by these presents does grant, bargain, sell and convey unto the Grantee in fee simple, all that certain lot or parcel of land situated in **Upper Little River** Township, **Harnett** County, North Carolina and more particularly described as follows:

Parcel ID No.: 130630 0076 / Reid No. 0007270

BEING all of Lot Number 2 according to Map Number 2006-13 recorded January 12, 2006 in the Harnett County Registry, said property containing 1.06 acres.

This is the same property conveyed to Rose K. Crowder by deed from Ted D. Brown, dated July 14, 2006 and recorded in Book 2254, Page 849-851, Harnett County Registry.

