

Kyle Brandewie



Duct Air Leakage Test

Property Address: 7129 Ross Road Erwin, NC 28339

The property listed above has been tested by Carolina Comfort Air Inc. whom is licensed HVAC contractor to meet the requirements of the North Carolina State 2012 Energy Conservation Code Section 403.2.2.

HVAC System Number: 1 Describe area of home served: Whole house

CFM25 Total: 60 Conditioned Floor Areas (CFA) served by system: 1371 s.f.

CFM25 X 100 divided by CFA = 4.3

Fan attachment location: hall

HVAC System Number: \_\_\_\_\_ Describe area of home served: \_\_\_\_\_

CFM25 Total: \_\_\_\_\_ Conditioned Floor Areas (CFA) served by system: \_\_\_\_\_ s.f.

CFM25 X 100 divided by CFA = \_\_\_\_\_

Fan attachment location: \_\_\_\_\_

Signature of Tester: Rodrigo Cortes Date: \_\_\_\_\_

1<sup>st</sup> Floor

2<sup>nd</sup> Floor

AH

Model #: \_\_\_\_\_

Serial #: \_\_\_\_\_

HS

Model #: \_\_\_\_\_

Serial #: \_\_\_\_\_

HP

Model #: \_\_\_\_\_

Serial #: \_\_\_\_\_

AH

Model #: \_\_\_\_\_

Serial #: \_\_\_\_\_

HS

Model #: \_\_\_\_\_

Serial #: \_\_\_\_\_

HP

Model #: \_\_\_\_\_

Serial #: \_\_\_\_\_

Clayton  
5212 US 70 Bus. W.  
Clayton, NC 27520  
(919) 550-7711  
NC HVAC Lic #31589

Raleigh  
6708 Westborough Dr.  
Raleigh, NC, 27612  
(919) 977-4500  
NC HVAC Lic #20515

Jacksonville  
149 Rea St.  
Jacksonville, NC 28546  
(910) 219-1061  
NC HVAC Lic #32508

Dunn  
200 Emmett Rd.  
Dunn, NC 28334  
(910) 339-2374  
NC HVAC Lic #29077