



Carolina
Comfort Air Inc.

Ashley Wright

Duct Air Leakage Test

Property Address: 689 Silas Moore Road Coats, NC 27521

The property listed above has been tested by Carolina Comfort Air Inc. whom is licensed HVAC contractor to meet the requirements of the North Carolina State 2012 Energy Conservation Code Section 403.2.2.

HVAC System Number: 1 Describe area of home served: Whole house

CFM25 Total: 60 Conditioned Floor Areas (CFA) served by system: 1105 s.f.

CFM25 X 100 divided by CFA = 5.4

Fan attachment location: Hall

HVAC System Number: _____ Describe area of home served: _____

CFM25 Total: _____ Conditioned Floor Areas (CFA) served by system: _____ s.f.

CFM25 X 100 divided by CFA = _____

Fan attachment location: _____

Signature of Tester: Rodrigo Cordes Date: 01-07-2019

1st Floor

2nd Floor

Model #: 4WCY5024A1000A

Serial #: 181311290L

HS

Model #: BAVHTRV108FA

Serial #: 8461T19823

HP

Model #: _____

Serial #: _____

AH

Model #: _____

Serial #: _____

HS

Model #: _____

Serial #: _____

HP

Model #: _____

Serial #: _____

Clayton
5212 US 70 Bus. W.
Clayton, NC 27520
(919) 550-7711
NC HVAC Lic #31589

Raleigh
6708 Westborough Dr.
Raleigh, NC, 27612
(919) 977-4500
NC HVAC Lic #20515

Jacksonville
149 Rea St.
Jacksonville, NC 28546
(910) 219-1061
NC HVAC Lic #32508

Dunn
200 Emmett Rd.
Dunn, NC 28334
(910) 339-2374
NC HVAC Lic #29077