

Kim systems				ke Atwood performanc		23-2741 ems.com
Property Address	146 Crystal Springs Dr Sanford					
HVAC Contractor	Comfort First					
HVAC System Number						
Data Collection	76					
Describe area of home	served:					
CFM25 Total:			33		0	0
Conditioned Floor Area	902		1	1	1	
(CFM25 x 100 divided by			0	0		
CFM25/100sf		3.66	0.00	0.00	0.00	
Tester Information	1					
Company Name	Performance Home System	ıs				
Name of Tester	Michael Atwood					
Tester Certification	Envelop Professional					
Tester Certification ID	BPI ID# 5028752					
Equipment ID						
Gauge Name/Serial	DG700 sn-34393-7-700					
Fan Serial	11643					
Date of Calibration	4/15/2021					
Energy Efficiency Cetr	ification					
CFM50		_	0			
Conditioned Floor Area			0			
Room Height			0			
Conditioned Volume Ar			0			
0.30 CFM50/SFSA			0.00			
5 ACH50			0.00			

ENERGY EFFICIENCY CERTIFICATE

401.9

Builder, Permit Holder or Registered Design Professional

Print Name: Comfort First

Signature:

Property Address:

146 Crystal Springs Dr Sanford

Insulation Rating - List the value covering largest area to all that apply

Ceiling/Roof	R-
Wall	R-
Floor	R-
Closed Crawl Space Wall	R-
Closed Crawl Space Floor	R-
Slab	R-
Basement Wall	R-

Fenestration:

U-Factor

Solar Heat Gain Coefficient (SHGC)

Building Air Leakage

ACH50) (Target 5.0) CFM50/SFSA (Target .30)

0.00

Name of Tester - Co	mpany Perfori	mance Home Systems
Michael Atwood	Envelop Professional	BPI ID# 5028752
29-Apr-21		910-723-2741

DUCTS

Insulation	R-8
Total Duct Leakage Test Result (sec.403.2.2)	3.66
CFM25 Total /100SF [Target 6]	0.00
CFM25 Total /100SF [Target 6]	0.00
CFM25 Total /100SF [Target 6]	0.00

Name of Tester - Company Performance Home Systems
Michael Atwood Envelop Professional BPI ID# 5028752
29-Apr-21 910-723-2741



Performance Home Systems Mike Atwood Building Analyst 910-723-2741

mike@performancehomesystems.com