

# OPERATIONS PERMIT

Name: (owner) Jimmy Wayne Barber  New Installation  Septic Tank  
 Property Location: SR# \_\_\_\_\_  Repairs  Nitrification Line  
 Subdivision \_\_\_\_\_ Lot # \_\_\_\_\_  
 Tax ID # \_\_\_\_\_ Quadrant # \_\_\_\_\_  
 Contractor: Jerry Stephenson Registration # \_\_\_\_\_

Basement with Plumbing:  Garage:

Water Supply:  Well  Public  Community

Distance From Well: 50 ft.

**Following are the specifications for the sewage disposal system on above captioned property.**

Type of system:  Conventional  Other Pump to Polystyrene Aggregate Trench System

Size of tank: Septic Tank: 6000 gallons Pump Tank: 1000 gallons

Subsurface No. of exact length width of depth of  
 Drainage Field ditches 1 of each ditch 150 ft. ditches 3 ft. ditches 18 in.

French Drain Required: \_\_\_\_\_ Linear feet

Date: 4/6/2004

Inspected by: Bryan M. R.S.  
Environmental Health Specialist

PERMIT NO. 17956

