


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____ DATE _____

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	L	L	L	L						
SLOPE (%)	.1940	2	2	2							
HORIZON 1 DEPTH		0-12	0-18	0-12	0-18						
Texture Group	.1941(A)(1)	LS	LS	LS	LS						
Consistence	.1941	FR									
Structure	.1941(A)(2)	GN									
Mineralogy	.1941(A)(3)	NSNP									
HORIZON 2 DEPTH		12-48	18-48	12-48	18-48						
Texture Group	.1941(A)(1)	SL	SL	SL	SL						
Consistence	.1941	FR									
Structure	.1941(A)(2)	GL									
Mineralogy	.1941(A)(3)	NSNP									
HORIZON 3 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
PERCENT WETNESS	.1942	36	38	40	38						
RESTRICTIVE HORIZON	.1944										
PERCENT PROLITE	.1943/.1956										
PERCENT CLASSIFICATION	.1948										
PERCENT LONG TERM											
PERCENT ACCEPTANCE RATE	.1955	.6	.7	.6	.7						

2x100'



BARN

SEPTIC TANK

DECK

WELL

HOUSE

CAR PORT

COUNTY WATER