Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Available Space (.1945) System Type(s) Site LTAR

Owner: Address: Proposed Facility: Location of Site: Water Supply: Evaluation Method Type of Wastewate		Property Recorded: Public Individual Well Spring Other od: Auger Boring Pit Cut									
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS						
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	W	1942 Soil etness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
	153%	0-19	6/4	The NINE	,						
		19-31	SBUSCI	K-SSIP	104/0	7/1071"				PS.5	
-						40					
									-		
Description Initial Repair System Other Factors (.1946):											
Descrip	/1.O11	System			Site Classification (.1948): Evaluated By: Others Present: Ot						
Available Space (.1945)					Evaluated By:						
System				25%	Others Present: M. Dav.>						

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET	
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE	II	S-SAND LS-LOAMY SAND SL-SANDY LOAM	1.2 - 0.8 0.8 - 0.6	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY	
N-NOSE SLOPE H-HEAD SLOPE CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	L-LOAM SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		VS-VERY STICKY NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC	

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY
PR-PRISMATIC

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY 0.4 - 0.1

EXPANSIVE

C-CLAY SC-SANDY CLAY

ΓV

Show profile locations and other site features (dimensions, references or benchmark, and North)