**		
HTE#		

HA ETT COUNTY HEALTH DEPAR' NT LINVIRONMENTAL HEALTH SECTION

17675

OPERATIONS PERMIT

	<u> </u>					
Name: (owner)	toletha !	DAUES	_ New	Installation] Septic	Γank Repair
Property Location: SR#	Lot	# Trunck Tax ID	#	(Quadrant	#
Contractor: Gerslo	Terple			Registr	ation#_	
Basement with Plumbir						
Water Supply: We We Distance From Well:						
Following are the spec	cifications for	the sewage disp	osal system	on above cap	tioned p	roperty.
Type of system:	Conventional	Other 25	% Reduce	Lia Syste	_	
Size of tank: Septic T	ank: Forsta	gallons Pu	ımp Tank: _	ga	illons	
Subsurface N Drainage Field d	No. of litches3	exact length of each ditch	70 ft.	width of ditches 3	_ ft.	depth of ditches 30 in.
French Drain Required:	:	Linear feet	Date:	6-/	6-05	
French Drain Required: PERMIT NO. 22025			Inspec	cted by:	mes C	Manhante
	Burne	Existens Home			work to	* * * * * * * * * * * * * * * * * * *
		SR 152	1 Gless	ns Cirle		