

Certificate of Completion

Owner Ed Curran Address Angu
 (MUST BE FILLED IN) (MAILING ADDRESS)
 Contractor " Address "
 (MAILING ADDRESS)
 Location of Premises Benton Place Lot #6
 (SUBDIVISION, STREET OR ROAD NAME OR NUMBER, LOT NO.)
SR 1504

Details of Septic Tank System

Kind of Material for Tank: Concrete Other _____
 Size of Tank: Capacity 1000 Gallons
 Subsurface Drainage Field No. of Ditches 2 Exact Length of each Ditch 100 Width of Ft. Ditches 3 Depth of Ft. Ditches 24 Inches
 Square Feet in Absorption Field 600 Surface Drainage Required _____ Linear Ft. _____
 Inspected by [Signature] (SANITARIAN)
 Permit No. 4541 Date 25 Apr 90

