

Certificate of Completion

No. 4142

Owner SM Mathias Address Argies
(MUST BE FILLED IN) (MAILING ADDRESS)

Contractor Curley Enterprise Address Selma
(MAILING ADDRESS)

Location of Premises Benton Place #9
(SUBDIVISION, STREET OR ROAD NAME OR NUMBER, LOT NO.)

SR1504

Details of Septic Tank System

Kind of Material for Tank: Concrete Other _____


Size of Tank: Capacity 900 Gallons

Subsurface Drainage Field No. of Ditches 2 Exact Length of each Ditch 100 Ft. Width of Ditches 3 Ft. Depth of Ditches 24-30 Inches

Square Feet in Absorption Field 600 Surface Drainage Required _____ Linear Ft.

Inspected by [Signature] (SANITARIAN)

Permit No. 4462 Date 20 Apr 90



Benton Place Dr → to SR1504