

Certificate of Completion

No. 4317

Owner Ed Currin Address 6390 Winberly Rd Willow Springs
(MUST BE FILLED IN) (MAILING ADDRESS)

Contractor Same Address _____
(MAILING ADDRESS)

Location of Premises Benton Place Subdivision Lot # 15
(SUBDIVISION, STREET OR ROAD NAME OR NUMBER, LOT NO.)
SR 1504

Details of Septic Tank System

Kind of Material for Tank: Concrete Other _____

Size of Tank: Capacity 1000 Gallons

Subsurface Drainage Field No. of Ditches 3 Exact Length of each Ditch 100 Ft. Ditches 3 Width of Ft. Ditches 24-30 Depth of Ditches 24-30 Inches

Square Feet in Absorption Field 900 Surface Drainage Required _____ Linear _____ Ft.

Inspected by Mike Eaker
(SANITARIAN)

Permit No. 4461 (NCP) Date 3/28/90

