

Certificate of Completion

No. ⁴ 4444

Owner William R. Cash Address _____
(MUST BE FILLED IN) (MAILING ADDRESS)

Contractor Jerry Pheasant Address _____
(MAILING ADDRESS)

Location of Premises SR 1504 Benton Place Sub. Lot # 29
(SUBDIVISION, STREET OR ROAD NAME OR NUMBER, LOT NO.)

Details of Septic Tank System

Kind of Material for Tank: Concrete Other _____

Size of Tank: Capacity 1000 Gallons

Subsurface Drainage Field No. of Ditches 3 Exact Length of each Ditch 100 Ft. Ditches 3 Width of Ditches 22 Inches

Square Feet in Absorption Field 900

Surface Drainage Required _____ Linear Ft.

Inspected by Mike Eate
(SANITARIAN)

Permit No. 4553 Date 3/1/90

