

## Certificate of Completion

Owner Russell Lamm Address Angin  
 (MUST BE FILLED IN) (MAILING ADDRESS)  
 Contractor Larry Sharpe Address Sanford  
 (MAILING ADDRESS)  
 Location of Premises off SR 1504  
 (SUBDIVISION, STREET OR ROAD NAME OR NUMBER, LOT NO.)  
Benton Place II lot #42

## Details of Septic Tank System

Kind of Material for Tank:  Concrete  Other \_\_\_\_\_  
 Size of Tank: Capacity 1000 Gallons  
 Subsurface Drainage Field No. of Ditches 3 Exact Length of each Ditch 80 Width of Ft. Ditches 3 Depth of Ft. Ditches 24 Inches

Square Feet in Absorption Field \_\_\_\_\_

Surface Drainage Required \_\_\_\_\_ Linear Ft.

Inspected by Charles Wood Jr.  
 (SANITARIAN)

Permit No. 5805 Date 11/05/91

