

**SITE/SOIL EVALUATION FOR ON-SITE TREATMENT**

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH		0-26	0-42							
Texture Group	.1941(A)(1)	LS	LS							
Consistence	.1941	VF <sub>r</sub>	VF <sub>r</sub>							
Structure	.1941(A)(2)	G	G							
Mineralogy	.1941(A)(3)	NEV	NEV							
HORIZON 2 DEPTH		20-42								
Texture Group	.1941(A)(1)	SL								
Consistence	.1941	VF <sub>r</sub>								
Structure	.1941(A)(2)	G								
Mineralogy	.1941(A)(3)	NEV								
HORIZON 3 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942									
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/.1956									
CLASSIFICATION	.1948	S	S							
LONG TERM ACCEPTANCE RATE	.1955	0.8	0.8							

