


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH		0-30	0-36	0-24						
Texture Group	.1941(A)(1)	LS	LS	LS						
Consistence	.1941	VFr	VFr	VFr						
Structure	.1941(A)(2)	G	G	G						
Mineralogy	.1941(A)(3)	WEV	WEV	WEV						
HORIZON 2 DEPTH		30-42	36-42	24-42						
Texture Group	.1941(A)(1)	SL	SL	SL						
Consistence	.1941	VFr	VFr	VFr						
Structure	.1941(A)(2)	G	G	G						
Mineralogy	.1941(A)(3)	WEV	WEV	WEV						
HORIZON 3 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942									
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/.1956									
CLASSIFICATION	.1948	S	S	S						
LONG TERM ACCEPTANCE RATE	.1955	0.8	0.8	0.8						



Ripley Rd