

# OPERATIONS PERMIT

Name: (owner) Ronald Strong  New Installation  Septic Tank  
 Property Location: SR# 1111  Repairs  Nitrification Line  
 Subdivision Seven Oaks Lot # 18  
 TAX ID# \_\_\_\_\_ Quadrant # \_\_\_\_\_  
 Contractor: GARNER BackHoe Rndford NC Registration # \_\_\_\_\_

Basement with Plumbing:  Garage:   
 Water Supply:  Well  Public  Community  
 Distance From Well: 50 min ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system:  Conventional  Other \_\_\_\_\_  
 Size of tank: Septic Tank: 1000 gallons Pump Tank: \_\_\_\_\_ gallons  
 Subsurface Drainage Field No. of ditches 2 exact length of each ditch 75 ft. width of ditches 3 ft. depth of ditches 18-30 in.  
 French Drain: \_\_\_\_\_ Linear feet

Date: 3-12-98

PERMIT NO. 14110

Inspected by: J. WARS  
Environmental Health Specialist

