## **CERTIFICATE OF COMPLETION / OPERATIONAL PERMIT**

New Installation	Septic Tank
☐ Repairs	•
Lot # 8-59	
Quadrant #	
Registration #	
у	
sal system on above o	captioned property.
Tank: 1000 gallor width of ft. ditches 3 ft.	ns
11 22 35	
ate:	1 1 0
aspected by::	266
Environmental	Health Specialist
	LPC part
	Repairs  Lot # \( \subseteq - \supersquare \)  Quadrant #  Registration #  y  sal system on above of the Countries A    Tank: \( \left  \frac{1000}{2000} \)  gallon width of ft. ditches3 ft.  ate: \( \left  \frac{120-9}{2000} \)  ate: \( \left  \frac{120-9}{2000} \)  aspected by:: \( \left  \frac{1}{2000} \)  aspected by:: \( \left  \frac{1}{2000} \)