CERTIFICATE OF COMPLETION / OPERATIONAL PERMIT

Name: (owner) Danny Norrys	New Installation Septic Tank Repairs Nitrification Line
Property Location: SR#27	☐ Repairs Nitrification Line
Subdivision Mire Br.	anch Lot# 69
Contractor: Ted Brown	Registration # //
Basement with Plumbing: Garage:	
Water Supply: Well Public	Community
Distance From Well: ft.	
Following are the specifications for the sewa	age disposal system on above captioned property.
Type of system: Conventional Other	
Size of tank: Septic Tank: 7000 gallons	Pump Tank: gallons
Subsurface No. of exact lengt of each ditches	th 80 ft. ditches 3 ft. depth of 30-18 in.
French Drain: Linear feet	Introlan 1
RMIT NO. 6557	Date: 10/28/92 Inspected by:: Charles Hope
	Environmental Health Specialist
	Pump to Avea Repair Avea H
	- www
	griss