

Certificate of Completi...

No 3532

Owner Rufus R. Anderson Address _____ (MAILING ADDRESS)
 (MUST BE FILLED IN)

Contractor Jerry Pleasant Address _____ (MAILING ADDRESS)

Location of Premises Briarwood Subdivision SR 1412
 (SUBDIVISION, STREET OR ROAD NAME OR NUMBER, LOT NO.)

Lot # 31, 30, 32

Details of Septic Tank System

Kind of Material for Tank: Concrete Other _____

Size of Tank: Capacity 1000 Gallons

Subsurface Drainage Field No. of Ditches 3 Exact Length of each Ditch 80 Ft. Width of Ditches 3 Ft. Depth of Ditches 22 Inches

Square Feet in Absorption Field 720 Surface Drainage Required _____ Ft. Linear

Inspected by Mike E. K. (SANITARIAN)

Permit No. 3554, 3555, 3553 Date 5/18/88

