

ARNETT COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH SECTION

No 12325

Attempt To
Repair

OPERATIONS PERMIT

Name: (owner) Ike Akor New Installation Septic Tank
Property Location: SR# 1111 Marku P Repairs Nitrification Line
Subdivision _____ Lot # 2-B
TAX ID# _____ Quadrant # _____
Contractor: W. Sharp Registration # _____

Basement with Plumbing: Garage:
Water Supply: Well Public Community
Distance From Well: 55 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other _____

Size of tank: Septic Tank: 3x 1000 gallons Pump Tank: _____ gallons

Subsurface Drainage Field No. of ditches 2x2 exact length of each ditch 2x50 ft. width of ditches 3 ft. depth of ditches 18-2 in.

French Drain: _____ Linear feet

Date: 7-8-99

PERMIT NO. 10936

Inspected by: J. Williams
Environmental Health Specialist

