

# Certificate of Completion

Owner Roscoe W. Betha Jr. Address Bradway  
(MUST BE FILLED IN) (MAILING ADDRESS)

Contractor Wayne Sharpe Address Swan station  
(MAILING ADDRESS)

Location of Premises SR 1278 lot 1 Quail Acres  
(SUBDIVISION, STREET OR ROAD NAME OR NUMBER, LOT NO.)

## Details of Septic Tank System

Kind of Material for Tank:  Concrete  Other \_\_\_\_\_

Size of Tank: Capacity 1000 Gallons

Subsurface Drainage Field No. of Ditches 3 Exact Length of each Ditch 100 Ft. Ditches Width of 3 Ft. Ditches Depth of 24 Ft. Ditches 24 Inches

Square Feet in Absorption Field \_\_\_\_\_ Surface Drainage Required \_\_\_\_\_ Linear Ft. \_\_\_\_\_

Inspected by Frank H. Byrd BS (SANITARIAN)

Permit No. 5197 Date 04/03/91

