ATTEMPT TO HTE REPAIR

H. IETT COUNTY HEALTH DEPAR ENTENVIRONMENTAL HEALTH SECT N

16727

OPERATIONS PERMIT

Name: (owner) Kyle A. Hayden	☐ New Installation 🔀 Septic Tank
Property Location: SR#	Repairs Nitrification Lin
Subdivision	Lot # 3+4
Tax ID #	Quadrant #
Contractor: IVEY JOHNSON	Registration #
Basement with Plumbing:	
Water Supply: ☐ Well ☑ Public ☐ Community	
Distance From Well: 50 ft.	
Following are the specifications for the sewage disposal sy	stem on above captioned property.
Type of system: Conventional Other <u>Pume</u>	To POLY. AGG. TRENCH
Size of tank: Septic Tank: 1000 gallons	Pump Tank: 1000 gallons
Subsurface No. of exact length Drainage Field ditches 3 of each ditch 60 ft	
French Drain Required:Linear feet	
	Date: 1/26/2005
	Inspected by: Sur Misails
PERMIT NO. 21382	Environmental Health Specialist
	* TANKS & LINES CHECKED ON
	* PUMP & ALARM STILL TO BE
(F)	CHECKED
Movee Movee	DOR-2-LE