


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-14	0-18	0-22	0-10	0-10	0-14	0-12			
Texture Group	.1941(A)(1)	LS/SL	LS/SL	LS/SL	US/UL	US/UL	US/UL	US/UL			
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 2 DEPTH		14-32	18-30	22-34	10-22	10-22	14-30	12-26			
Texture Group	.1941(A)(1)	SCL	SCL	SCL	SCL	SCL	SCL	SCL			
Consistence	.1941	VF _i	VF _i	Fi	VF _i	VF _i	VF _i	Fi			
Structure	.1941(A)(2)	SBL	SBL	SBL	SBL	SBL	SBL	SBL			
Mineralogy	.1941(A)(3)	SEXP	SEXP	SEXP	SEXP	SEXP	SEXP	SEXP			
HORIZON 3 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942	28"	27"	32" PM	20"	22"	28"	22"			
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948	PS	PS	PS	OUT	OUT	PS	OUT			
LONG TERM ACCEPTANCE RATE	.1955	.3	.3	.4	OUT	OUT	.4/3	OUT			

Boeing



3x100' line at 15" depth w/3" cover required
more house 10' forward to 65!!

