

# SOIL/SITE EVALUATION

(Continuation Sheet)

DEPARTMENT OF ENVIRONMENT, HEA  
AND NATURAL RESOURCES  
DIVISION OF ENVIRONMENTAL HEALTH

Lot 11  
Hearth Brook S/D

PROPERTY ID #: \_\_\_\_\_  
DATE OF EVALUATION: 4-27-96  
COUNTY: Hannett

P R O F I L E  #	.1940 LAND- SCAPE POSITION/ SLOPE %	HORI- ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941)		OTHER PROFILE FACTORS				PROFILE CLASS & LTAR
			.1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	.1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	
4576	L	0-48	LS	VFR	4 1/2" 32"				.9
		<del>36-48</del>							
4577	L	0-30	LS	VFR				.8	
		30-48	SL	VFR					
4579	L	0-20	LS	VFR				.7	
		20-48	SL to SCL	FR					
4579	L	0-48	LS	VFR				.9	

COMMENTS: off Endy